

(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 028878

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR
Bass Enterprises Production Co

RECEIVED

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
P O Box 2760 Midland, Texas 79702-2760

SEP 29 '88

Sur: Sec. 8, T23S, R31E Unit Letter M
BHL: Sec. 7, T23S, R31E Unit Letter O

O. C. D.
ARTESIA, OFFICE

14. PERMIT NO.

30-015-24780

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3339' KB 3311' GL 3338' DF

7. UNIT AGREEMENT NAME

James Ranch Unit

8. FARM OR LEASE NAME

James Ranch Unit

9. WELL NO.

15

10. FIELD AND POOL, OR WILDCAT

Los Medanos Morrow Gas

11. SEC., T., R., M., OR BLK. AND

SURVEY OR AREA

Sur: Sec. 8, T23S, R31E

BHL: Sec. 7, T23S, R31E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other) Clean out and Stimulate

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Remove Well Head & set BOPE. Load Tbg. and Circ. 9 ppg. Brine Wtr.
2. Pull Tubing and Packer
3. Run in hole with bit and scraper
4. Pull out of hole
5. Stimulate Perfs. 14,486' - 14,576' using 10% HCl Acid with additives using Baker SAP Tool

18. I hereby certify that the foregoing is true and correct

SIGNED

R. L. Hutchens

TITLE Senior Production Clerk

DATE 9-20-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

9-28-88

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.