

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

CONFIDENTIAL
AUG 14 1985
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	LG-6449	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Dry	7. Unit Agreement Name
2. Name of Operator Exxon Corp.	8. Farm or Lease Name New Mexico ER State
3. Address of Operator P. O. Box 1600, Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER I 2251 FEET FROM THE South LINE AND 666 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 23S RANGE 25E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) GR-3866, DF-3877, KB-3878	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well was plugged and abandoned on 7/17/85 as follows:

Set plug at 3170 w/10 sx cmt.
CIBP at 2586 w/35' cmt.
Set plug at 1910 w/20 sx cmt.
Set plug at 1650 w/35 sx cmt.
Set plug at 1338 w/30 sx cmt.
Set plug at 482 w/30 sx cmt.
Set plug 50' - surface w/15 sx cmt.
Cut off wellhead and install dry hole marker.

Post ID-2
8-30-85
p4A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Michael L. Lippert TITLE Unit Head DATE 8/12/85

APPROVED BY Danell Moore TITLE Geologist DATE 7/16/86

CONDITIONS OF APPROVAL, IF ANY: