

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY P. O. BOX 2088
SANTA FE, NEW MEXICO 87501
MAY 21 1985
O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator: Ray Westall
3. Address of Operator: P.O. Box 4 Loco Hills, New Mexico 88255
4. Location of Well:
UNIT LETTER 0 1710 FEET FROM THE East LINE AND 580 FEET FROM
THE South LINE, SECTION 28 TOWNSHIP 23S RANGE 28E NMPM.
10. Field and Pool, or Wildcat: Und. S. Culebra Bluff-BS
7. Unit Agreement Name:
8. Farm or Lease Name: Buckaroo
9. Well No.: 1
11. Elevation (Show whether DF, RT, GR, etc.): 3059. GL
12. County: Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ OTHER ☐
SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER Perforating & Treatment ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-15-85 Perforated: 7280-7300
5-16-85 Acidized: Pumped 4,000 gal. SRA 15% acid down well.
5-18-85 Fracture: Frac'd w/30,000 gal. 60# gel, 80,000# 20/40 sand.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ray Westall TITLE Operator DATE 5-20-85

APPROVED BY ORIGINAL SIGNED BY LARRY BROOKS GEOLOGIST - NMCD TITLE _____ DATE MAY 22 1985
CONDITIONS OF APPROVAL, IF ANY: