NO DE CORIES RECE	1450					
	DISTRIBUTION			Form C-103 Supersedes Old		
····	T necessary State			C-102 and C-103		
SANTA FE	NEW	MEXICO OIL CONS	ERVITION COMMISSION	Effective	1-1-65	
FILE		NOV 10 1986		Con today or		
U.S.G.S.		MA TO 1200		Sa. Indicate T	1	
LAND OFFICE		O. C. D.		State	Fee X	
OPERATOR		ARTESIA, OFFICE	1	5. State Off &	Gas Lease No.	
					mmm	
(DO NOT USE	SUNDRY NOTICES A	ND REPORTS ON	WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)					ment Name	
OIL WELL	GAS X OTHER.			7. Olik Agree	nem Name	
2. Name of Operator					ase Name	
TXO Production Corp.						
3. Address of Operator				9. Well No.	Delta Fee "C"	
900 Wilco Bldg. Midland, Texas 79701				1		
4, Location of Well				No. Field and	Pool, or Wildcat	
UNIT LETTER	C 1980	West	LINE AND 990 FEET			
UNIT CETTER	FEET I	FROM THE	LINE AND FEET	FROM TITTI		
THE North Line, SECTION 12 TOWNSHIP 22-S RANGE 27-E NMPM.						
THE LINE, SECTION TOWNSHIP RANGE Z/ T NMPM.				MPM. (		
	15. EI	evation (Show whether	DF, RT, GR, etc.)	12. County	<del>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</del>	
Allllllll	111111111111111111111111111111111111111	93 GL & 3109 I	KB	Eddy		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:						
	NOTICE OF INTENTION TO	<b>'•</b>	SUBSEQU	ENI REPORT C	∤ <b>F:</b>	
PERFORM REMEDIAL W	ORK	PLUG AND ABANDON	REMEDIAL WORK			
TEMPORARILY ABANDO			COMMENCE DRILLING OPNS.		TERING CASING	
PULL OR ALTER CASIN	<b>7</b>	HANGE PLANS	CASING TEST AND CEMENT JOB X	PE	G AND ABANDONMENT	
			OTHER			
OTHER						
17. Describe Propose work) SEE RULE	d or Completed Operations ( <i>Clearly</i> 11103.	state all pertinent det	ails, and give pertinent dates, incli	uding estimated date	of starting any proposed	
. 10 14 06	D ' 11' 44H 1 1			•		
10-14-86 Drilling 11" hole.						
10-10-80	10-16-86 TD'ed 11" hole. Ran 8-5/8" casing. Cement w/1400sx Western lite and tailed in w/3 sx 2% "C". Circulated 175sx to pit. Set @ 2700'. PD @ 8:45pm. ND BOP. Cut casi:					
	SX 2% "C". Circulated	1/5sx to pit.	Set @ 2700'. PD @	8:45pm. ND	BOP. Cut casing	
10 17 06	NU BUP. Test BUP & ma	nitold to 5000	O#. OK. Test hydril to	o 2500. NU RE	1.	
10-17-86 Tested casing to 1000#. OK. Drilling 7-7/8" hole.						
11-04-86 TD'ed 7-7/8" hole. Circ f/logs. Logging.						
11-05-86 Loggers TD@ 10,071'. RU & ran 4-1/2" casing.						
11-06-86 Finished running 4-1/2" casing. Cemented w/600sx 'H" & 350sx 50/50 POZ and 100sx						
''H'' neat. Set @ 10,070'. PD @ 10:15pm. RR 4:30am. 11-07-86 Top of cement @ 3900'. Ran temp survey.						
11-07-86 Top of cement @ 3900'. Ran temp survey.						
16. I hereby certity th	at the information above is true and	i complete to the best	of my knowledge and belief.			
SIGNED UUU	ia Denderson	J Eng	ineering Assistant		11-07-86	
Original Signed By						
APPROVED BY	les A. Cl	7171 F	·.	· N	OV 10 1986	
CONDITIONS OF AP	Supervisor	District 11	· · · · · · · · · · · · · · · · · · ·	DATE	* 1000	
INNS OF AP	TRUYAL, IF ANY:					

ting the state of the state of