ENERGY AND MINERALS DEPARTMENT					Form C-103
NO. OF COPIES RECEIVED	OIL CONSER	VATION DIVISION			Revised 10-1-78
DISTRIBUTION	RECEIVED	TE BOX 2088			
SANTA FE	SANTA FE, I	NEV MEXICO 87501	_		
FILE	FEB 04 1986			5a. Ind <u>ica</u> te	Type of Lease
U.S.G.S	FED V1 1300		_	State	Fee X
LAND OFFICE	O. C. D.	1		5. State Oil	& Gas Lease No.
OPERATOR	ARTESIA OFFICE ON W				
SUNDRY WOT			,	(XXXXXXXXXXXXXXXXX	*****
(DO NOT USE THIS FORM FOR PROPOS				(XXXXXXXXXXXXXXXXX	*****
RESERVOIR. USE "APPLICA	ATION FOR PERMIT-" (FO	ORM C-101) FOR SUCH			****
OIL GAS				7. Unit Agree	ment Name
WELL X WELL	OTHER			-	· · · · · · · · · · · · · · · · · · ·
. Name of Operator /			ļ	B. Farm or Le	
Read & Stevens, Inc. 🗸				Cass D	raw
Address of Operator			5	9. Well No.	
Post Office Box 1518, Roswell,	New Mexico 88202			2	
. Location of Well					Pool, or Wildcat
UNIT LETTER I. 890				Wildcat De	
THE South LINE. SECTION	24 TOWNSHIP	23S RANGE			XXXXXXXXXXXXXXXXXXXXXXX
****	5. Elevation(Show who		•)	12. County	
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX					
	PLUG AND ABANDON				
	CHANGE PLANS	OTHER Wate	LLING OPNS.	PLUG AN	G CASING D ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER escribe Proposed or Completed Op ated date of starting any propos	CHANGE PLANS	COMMENCE DRIL CASING TEST A OTHER Wate te all pertinent de 03.	LING OPNS. AND CEMENT JOB er Analysis etails, and give p	PLUG AN	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER escribe Proposed or Completed Op	CHANGE PLANS	COMMENCE DRIL CASING TEST A OTHER Wate	LLING OPNS.	PLUG AN	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER escribe Proposed or Completed Op ated date of starting any propos <u>Water Analysis</u> SG	CHANGE PLANS	COMMENCE DRIL CASING TEST A OTHER Wate te all pertinent de 03. 1-29-86 1.100	LLING OPNS. AND CEMENT JOB er Analysis etails, and give p 2-1-86 1.105	PLUG AN	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER escribe Proposed or Completed Op ated date of starting any propose <u>Water Analysis</u>	CHANGE PLANS	COMMENCE DRIL CASING TEST A OTHER Wate te all pertinent de D3.	LLING OPNS. AND CEMENT JOB er Analysis etails, and give p 2-1-86	PLUG AN	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER escribe Proposed or Completed Op ated date of starting any propos <u>Water Analysis</u> SG Res	CHANGE PLANS Derations(Clearly stat sed work) SEE RULE 110 3: 1-27-86 1.100 .068 @ 72 %	COMMENCE DRIL CASING TEST A OTHER Wate te all pertinent de 03. 1-29-86 1.100 .063 @ 65 %	LLING OPNS. AND CEMENT JOB er Analysis etails, and give p 2-1-86 1.105 .063 2 65	PLUG AN	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER escribe Proposed or Completed Op ated date of starting any propos <u>Water Analysis</u> SG Res Ph Ca	CHANGE PLANS Derations(Clearly stat sed work) SEE RULE 110 3: 1-27-86 1.100 .068 @ 72°F 6.9	COMMENCE DRIL CASING TEST A OTHER <u>Wate</u> te all pertinent de 03. 1-29-86 1.100 .063 @ 65% 6.5	LLING OPNS. AND CEMENT JOB er Analysis etails, and give p 2-1-86 1.105 .063 G 65 6.5	PLUG AN	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Describe Proposed or Completed Op ated date of starting any propose <u>Water Analysis</u> SG Res Ph	CHANGE PLANS	COMMENCE DRIL CASING TEST A OTHER <u>Wate</u> te all pertinent de 03. 1-29-86 1.100 .063 @ 65% 6.5 5900	LLING OPNS. AND CEMENT JOB er Analysis etails, and give p 2-1-86 1.105 .063 2 65 6.5 4900	PLUG AN	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Describe Proposed or Completed Op hated date of starting any propose Water Analysis SG Res Ph Ca Mg C1	CHANGE PLANS Derations(Clearly stat and work) SEE RULE 110 3: 1-27-86 1.100 .068 @ 72 % 6.9 3330	COMMENCE DRIL CASING TEST A OTHER <u>Wate</u> te all pertinent de 03. 1-29-86 1.100 .063 @ 65% 6.5 5900 2100	LLING OPNS. AND CEMENT JOB ar Analysis etails, and give p 2-1-86 1.105 .063 a 65 6.5 4900 3060	PLUG AN	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Describe Proposed or Completed Op hated date of starting any propos Water Analysis SG Res Ph Ca Mg C1 SO ₄	CHANGE PLANS Derations(Clearly stat aed work) SEE RULE 110 3: 1-27-86 1.100 .068 @ 72 °F 6.9 3330 180 93,000	COMMENCE DRIL CASING TEST A OTHER Wate te all pertinent de 03. 1-29-86 1.100 .063 @ 65 % 6.5 5900 2100 87,000	LLING OPNS. AND CEMENT JOB er Analysis etails, and give p 2-1-86 1.105 .063 @ 654 6.5 4900 3060 89,000	PLUG AN	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Describe Proposed or Completed Op ated date of starting any propose Water Analysis SG Res Ph Ca Mg C1	CHANGE PLANS	COMMENCE DRIL CASING TEST A OTHER Wate te all pertinent de 03. 1-29-86 1.100 .063 @ 65 % 6.5 5900 2100 87,000	LLING OPNS. AND CEMENT JOB er Analysis etails, and give p 2-1-86 1.105 .063 @ 654 6.5 4900 3060 89,000 Lt.	PLUG AN	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Describe Proposed or Completed Option mated date of starting any proposed Water Analysis SG Res Ph Ca Mg C1 SO ₄ HCO ₃ Fe	CHANGE PLANS	COMMENCE DRIL CASING TEST A OTHER <u>Wate</u> te all pertinent de 03. 1-29-86 1.100 .063 @ 65% 6.5 5900 2100 87,000 Lt. - Hvy	LLING OPNS. AND CEMENT JOB er Analysis etails, and give p 2-1-86 1.105 .063 a 65 6.5 4900 3060 89,000 Lt. 60 Lt.	PLUG AN	D ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Describe Proposed or Completed Option mated date of starting any proposed Water Analysis SG Res Ph Ca Mg C1 SO ₄ HCO ₃ Fe	CHANGE PLANS	COMMENCE DRIL CASING TEST A OTHER <u>Wate</u> te all pertinent de 03. 1-29-86 1.100 .063 @ 65% 6.5 5900 2100 87,000 Lt. - Hvy	LLING OPNS. AND CEMENT JOB er Analysis etails, and give p 2-1-86 1.105 .063 a 65 6.5 4900 3060 89,000 Lt. 60 Lt.	PLUG AN	D ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER escribe Proposed or Completed Op ated date of starting any propose Water Analysis SG Res Ph Ca Mg C1 SO ₄ HCO ₃ Fe	CHANGE PLANS	COMMENCE DRIL CASING TEST A OTHER Wate te all pertinent de 03. 1-29-86 1.100 .063 @ 65 % 6.5 5900 2100 87,000 Lt. - Hvy and complete to the	LLING OPNS. AND CEMENT JOB er Analysis etails, and give p 2-1-86 1.105 .063 a 65 6.5 4900 3060 89,000 Lt. 60 Lt.	PLUG AN	D ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Describe Proposed or Completed Op hated date of starting any propose Water Analysis SG Res Ph Ca Mg C1 SO ₄ HCO ₃ Fe I hereby certify that the inform	CHANGE PLANS	COMMENCE DRIL CASING TEST A OTHER Wate te all pertinent de 03. 1-29-86 1.100 .063 @ 65 % 6.5 5900 2100 87,000 Lt. - Hvy and complete to the	LLING OPNS. AND CEMENT JOB er Analysis etails, and give p 2-1-86 1.105 .063 @ 65 6.5 4900 3060 89,000 Lt. 60 Lt. 60 Lt.	PLUG AN	D ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Describe Proposed or Completed Op mated date of starting any propos <u>Water Analysis</u> SG Res Ph Ca Mg C1 SO ₄ HCO ₃ Fe I hereby certify that the inform	CHANGE PLANS Derations(Clearly stat Sed work) SEE RULE 110 a: 1-27-86 1.100 .068 @ 72°F 6.9 3330 180 93,000 Nil 153 Nil mation above is true of Coriginal Signed By	COMMENCE DRIL CASING TEST A OTHER Wate te all pertinent de 03. 1-29-86 1.100 .063 @ 65 % 6.5 5900 2100 87,000 Lt. - Hvy and complete to the	LLING OPNS. AND CEMENT JOB er Analysis etails, and give p 2-1-86 1.105 .063 @ 65 6.5 4900 3060 89,000 Lt. 60 Lt. 60 Lt.	PLUG AN	D ABANDONMENT X es, including esti- ief. February 3, 1986



-