Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR OSIA, NM 88210 BUREAU OF LAND MANAGEMENT APR - 6 1995

FORM APPROVED

Budget Bureau No. 1004-0135 Expires: March 31, 1993

BUKEAU OF I	AND MANAGEMENT 13111 V 100			
SUNDRY NOTICES AND REPORTS ON WELLS		NM-45236		
Do not use this form for proposals to drill	6. If Indian, Allottee or Tribe Name			
	PERMIT - " for such proposals (ST	44		
SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation		
1. Type of Well Oil Y Gas	10 h 10 m	8. Well Name and No.		
Oil X Gas Well Other 2. Name of Operator		Sterling Silver		
Santa Fe Energy Resources, In	c \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	33" Fed #1	_	
3. Address and Telephone No.		9. API Well No. 30-015-25639		
550 W. Texas, Suite 1330, Midl	10. Field and Pool, or exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey De	Sand Dunes, West			
(E), 1980' FNL & 810' FWL, Se	(Atoka) Gas			
		11. County or Parish, State		
		Eddy NM		
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE (FACTION	_	
Notice of Intent	Abandonment	Change of Plans	_	
- -	X Recompletion	New Construction		
X Subsequent Report	Plugging Back	Non-Routine Fracturing		
	Casing Repair	Water Shut-Off		
Final Abandonment Notice	Altering Casing	• Conversion to Injection		
	Other	Dispose Water		
		(Note: Report results of multiple completion on W Completion or Recompletion Report and Log for	Vell	
3. Describe Proposed or Completed Operations (Clearly state all	pertinent details, and give pertinent dates, including estimate	l date of starting any proposed work. If well is directionally d	lrille	
give substituace locations and measured and true vert	cal depths for all markers and zones pertinent to this work.)	·		
12/21/94 thru 12/24/94:				
Set CIBP at 14,700' and dump 50'	cmt on top of plug.			
Acid wash tubing w/ 1000 gals 7-	1/2% acid.			
Perforate Morrow Paduca Sand at	14,566'-14,5/4' w/ 2 SPF. No	response from formation. Shut	;	
down for Holidays. 12/27/94 thru 1/1/95:				
	s and rec 25 RW Dumped 3000	gal 7 1/2% NoFe acid v/ 00		
Began swab testing. Made 18 runs and rec. 25 BW. Pumped 3000 gal 7-1/2% NeFe acid w/ 90 ball sealers and 350 SCF nitrogen. Slight ball action. Attempted to flow test. Rec. 48 BW				
and well died. Swapped 13 runs	recovering 20 BW. Flow well 2	hrs on 9/64" choke - no	•	
recovery. Swabbed 7 runs & reco	vered 4 BW. Shut down for Ho	idav and weekend.		
01/5/95 thru 01/08/95:		•		
Set CIBP @ 14,500' w/ 50' cmt on	top of plug. Set CIBP @ 14,1	50' w/ 50' cmt on top. Spot 2	250	
gals 7-1/2% NeFe HCl. Perforate	Lower Atoka @ 13,785'-13,807'	w/ 2 SPF (46 holes).		
01/12/95: Put well on line and begin flow	tostina			
ruc werr on time and begin flow	testing.			
14. I perchy certify that the foregoing is true and offrect			_	
	SUGKERS Sr. Production Clerk	Date March 3, 1995		
	Same St. Froduction City	Date 11d1 Cli 3, 1995	_	
(This space for Federal or State office use)		ACCEPTED FOR RECORD	_	
Approved by	Title	Pare		

* See Instruction on Rever	se Side CARLSBAD, NEW MEXICO
itle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any deper representations as to any matter within its jurisdiction.	artment or agercy of the United States any false, fictitious or flaudulent statements
Conditions of approval, if any:	J. Jara 4 1995
Approved by Title	ACCEPTED FOR RECORD