



333 Clay
P.O. Box 4648
Houston, Texas 77210-4648

(713) 646-4100

December 15, 1995

Oil Conservation Division
District II
P.O. Drawer DD
Artesia, NM 88210

Re: Revised Form C-105
SPC Rohmer No. 1 SWD
Sec. 23 T-22S R-27E
Eddy County, New Mexico

Gentlemen:

Enclosed, please find an amended Form C-105 and the schematic pertaining to the above referenced SWD.

Due to the detection of a small tubing leak on December 4, 1995, the Rohmer No. 1 was shut in. A new string of PVC lined 2 $\frac{7}{8}$ " tubing was installed on December 8, 1995. The 2 $\frac{7}{8}$ " x 5 $\frac{1}{2}$ " annulus was filled with 2% KCl and Packer Fluid. The annulus is isolated with a 2 $\frac{7}{8}$ " x 5 $\frac{1}{2}$ " Loc-Set Packer and was pressure tested to 300 psi for 30 minutes. A chart recorder was used, and the test was witnessed by a representative from your office.

The well was placed back in service on December 8, 1995 and normal operations resumed.

Sincerely,

Steward E. Rogers

encl.

cc: Owen Mobley
Faye Turman
Richard Lentz



SUBSIDIARY OF ASHLAND OIL INC.