



333 Clay
P.O. Box 4648
Houston, Texas 77210-4648

(713) 646-4100

January 18, 1996

Oil Conservation Division
District II
P. O. Drawer DD
Artesia, NM 88210

Reference: Revised Form C-103
SPC Rohmer No. 1 SWD
Sec. 23 T-22-S R-27-E
Eddy County, New Mexico


Gentlemen:

Enclosed, please find an amended Form C-103 and the schematic pertaining to the above referenced SWD.

Due to the detection of a small tubing leak on December 4, 1995, the Rohmer No. 1 was shut in. A new string of PVC lined 2 7/8" tubing was installed on December 8, 1995. The 2 7/8" x 5 1/2" annulus was filled with 2% KCl and Packer Fluid. The annulus is isolated with a 2 7/8" x 5 1/2" Loc-Set Packer and was pressure tested to 300 psi for 30 minutes. A chart recorder was used, and the test was witnessed by a representative from your office.

The well was placed back in service on December 8, 1995 and normal operations resumed.

Sincerely,


Steward E. Rogers

:jag

encl

c: Owen Mobley
Faye Turman
Richard Lentz