

45F
DP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

AUG 25 1992

O. C. D.
ARTESIA OFFICE

WELL API NO. 30-015-25866
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-3589
7. Lease Name or Unit Agreement Name Pauline ALB State
8. Well No. 6
9. Pool name or Wildcat Wildcat Bone Springs/Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> RE-ENTRY <input type="checkbox"/>
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210

4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 32 Township 23S Range 31E NMPM Eddy County
--

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3370.5' GR
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/> OTHER: Perforate, Treat <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
8-14-92. Re-entry cont'd. Casing splice at 6165'. Perforated 8037-45' w/14 .45" holes (2 SPF) as follows: 8037, 38, 39, 40, 43, 44 and 8045'. Acidized perms w/750g. 7½% NEFE. Frac w/1600g. linear gel, 10700g. XL, 25500# 20/40 sand. Perforated 7511-7936' w/62 .45" holes (2 SPF) as follows: 7868, 70, 72, 74, 82, 84, 86, 92, 93, 7932, 34 and 7936' (24). Acidized w/1500g. 7½% NEFE. Frac 7868-7936' w/2400g. linear prepad, 11000g. XL and 24000# 20/40 sand. Perforated 7762, 64, 66, 68, 7772, 74, 76, and 7778' (16), 7702, 03, 04, 05, and 7706' (10). Acidized 7762-78' and 7703-06' w/1500g. 7½% NEFE acid. Frac perms 7762-78' and 7702-06' w/10000g. 35# linear prepad, 22000g. 35# XL and 38000# 20/40 sand. Set RBP 7565', tested. Set packer 7433'. Perforated 7511, 13, 15, 23, 25 and 7529' (12). Acidize 7511-29' w/1000g. 7½% NEFE. Frac perms 7511-29' w/6000g. linear prepaid, 4000g. 35# XL and 22000# 20/40 sand. Unset packer at 7433' and RBP at 7565'. Retrieve RBP at 7961' and TOOH. Put well on pump. First production 8-23-92. NOTE: At first failure or 30 days, whichever occurs first, must pull well and run packer and swab test Bone Spring. This swab test will be used for application for downhole commingling Bone Spring and Delaware.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE	TITLE Production Supervisor	DATE 8-24-92
TYPE OR PRINT NAME Juanita Goodlett	TELEPHONE NO. 505/748-1471	

(This space for State Use)	ORIGINAL SIGNED BY
APPROVED BY	TITLE SUPERVISOR, DISTRICT I
CONDITIONS OF APPROVAL, IF ANY:	DATE AUG 28 1992