

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Santa Fe	
File	
BLM	
Land Office	
B of M	
Operator	

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

RECEIVED

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

JUN 19 89

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER ☒ SWD

2. Name of Operator
Parker & Parsley Petroleum Company

3. Address of Operator
P. O. Box 3178, Midland, Texas 79702

4. Well Location
Unit Letter H : 2069 Feet From The North Line and 632 Feet From The East Line
Section 27 Township 23-S Range 28-E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3033.1 GR

WELL API NO.
30-015-26122

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Pardue Farms 27

8. Well No.
8

9. Pool name or Wildcat
Delaware (Bell Canyon)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Perforate & acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-9-89 Perf. Cherry Canyon w/2 JSPF @4612 to 4662', 4592 to 4612', 4524 to 4564', 4484 to 4524', 4394 to 4444'. (Total 700 shots.)

6-12-89 Finish TIH w/134 jts. 2 7/8", 6.5#, L-80 EUE, 8RD IPC tbg & 15 jts. reg. 2 7/8" tbg. Set pkr. @4670'. Release on-off tool. Spot 12 bbls. 15% HCL NEFE f/4662-4300'. PU & LD 15 jts. reg. 2 7/8" tbg. Set 7" X 2 3/8" Elder Surlock ENP w/on-off tool w/1.781 F profile ENP nipple. Set pkr. @4298'. Release on-off tool. Displ hole w/140 bbls. pkr. fluid. Latch onto pkr. Pull 10 pts & set slips. Assemble WH. Pmp out pkr. plug @1600 psi. Acidized perfs f/4394 to 4612' w/5000 gal 15% HCL NEFE @7.2 BPM @2200 psi. Drop 800 B.S. Flush w/40 BFW.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Randy R. Johnson

TITLE

Operations Engineer

DATE

6-14-89

TYPE OR PRINT NAME

Randy R. Johnson

915
TELEPHONE NO. 683 4768

(This space for State Use)

APPROVED BY

APPROVED BY
DISTRICT II

TITLE

DATE

JUN 21 1989

CONDITIONS OF APPROVAL, IF ANY: