Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Revised 1-1-89

OH CONSEDUATION DIVISION

P.O. Box 1980, Hobbs, NM 88240		711014 D1 4121014	WELL API NO.
DISTRICT II	P.O. Box 2088 Santa Fe, New Mexico 87504-2088		30-015-26130
P.O. Drawer DD, Artesia, NM 88210	Saina i e, inew ivic	,Alco 01307 2000	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No.
( DO NOT USE THIS FORM FOR PR DIFFERENT RESE (FORM C	ICES AND REPORTS ON OPOSALS TO DRILL OR TO DE RVOIR. USE "APPLICATION FO 1-101) FOR SUCH PROPOSALS	EEPEN OR PLUG BACK TO A OR PERMIT	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL X WELL	OTHER		MAINTON (
2. Name of Operator	<u> </u>	JUL 12 89	8. Well No.
NEFF Oil and Gas 🗸	/		1
3. Address of Operator		O. C. D.	9. Pool name or Wildcap
150 Washington Ave. 4. Well Location	Suite 202 Santa Fe, N	New Mexico RESONOUTIVE	UND. HERRADURA CHERRY CANYON
	Feet From The North	1 Line and 198	Feet From The West Line
Section 29	3044.7 GR	Range <u>28E</u> whether DF, RKB, RT, GR, etc.)	NMPM Eddy County
11. Check NOTICE OF IN	Appropriate Box to Indi TENTION TO:		Report, or Other Data BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	IG OPNS. DPLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND	CEMENT JOB
OTHER:		OTHER:	
work) SEE RULE 1103.  Perforate 3360-68 3292-97, 3300-331  Propose to Pocing @ 3250'	w/2 JSPF. Swab 100% S 2 w/2JSPF. Acidize w/ A Well with Following: w/35' cement.	ulfur water. Set CIBP (	Perforate date of starting any proposed  2 3355w/ 25' cement. Perforate 2 100% Formation Water.
	0 w/25sx 0 w/25sx 0'w/25sx to Surface w/25sx.		
I hereby certify that the differention above is t	rycard complete to the best of my know	TITLE AGENT	DATE 6-28-89
SIGNATURE			TELEPHIONE NO. 622-7355
TYPE OR PRINT NAME Cane I ac	AL SIGNED BY		
( )	ILLIAMS		"BOAR A SM ASS

AJTROVED BY-

SUPERVISOR, DISTRICT IT