Form 3160-5 (November 1983) (Formerly 9-331	UN ED STATES DEPARTMENT OF THE INTERIOR COMPANIES OF THE BUREAU OF LAND MANAGEMENT	DESIGNATION AND BERIAL NO	
(Do not w	SUNDRY NOTICES AND REPORTS ON WELLS this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	NM-36975 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
WELL, L	AS X OTHER	7. UNIT AGREEMENT NAME	
2. NAME OF OPERA Santa Fe		8. FARM OR LEASE NAME	
3. ADDRESS OF OP	Energy Operating Partners, L.P. 25 09	Salt Draw 28 Federal	
500 W. Illinois, Suite 500, Midland, TX 79701 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		1 10. FIELD AND POOL, OR WILDCAT	
1980' FNL & 660' FEL, Sec. 28, T-24S, R-28E		Und. Malaga Morrow	
		11. SEC., T., B., M., OR BLK. AND SURVEY OR ARDA	
4. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	28, T-24S, R-28E	
API #30-015		12. COUNTY OR PARISH 13. STATE	
6.		Eddy NM	
	Check Appropriate Box To Indicate Nature of Notice, Report, or Ot		
TEST WATER SHUT-OFF PULL OR ALTER CASING		NT REPORT OF:	
FRACTURE TREA	WATER SHUT-OFF	REPAIRING WELL	
SHOOT OR ACIDI	ZE ABANDON* SHOOTING OR ACIDIZING	ALTERING CASING ABANDONMENT	
REPAIR WELL (Other)	CHANGE PLANS (Other) Set liner	V	
LESCHINE UNDOWN	ED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, in rk.).	f multiple completion on Well tion Report and Log form.)	
nent to this wo	EN OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, in If well is directionally drilled, give subsurface locations and measured and true vertical rk.).	scluding estimated date of starting any depths for all markers and zones perti-	
9-6-89:	Ran 5 $1/2$ " liner as follows: 71 jts 23# N-80 LT&C plus Hang liner from 9313' to 13,450' (TD).	s 27 jts 23# P-110 LT&C.	
9-7-89:	Cemented $w/650$ sx Premium $w/0.6\%$ Halad 22A, 0.4% CFR-3 stop. WOC 14 hrs (Option II). Tag cement at 8394'.	M 11). Tag cement at 8394'. Drill cement to 0176!	
9-8-89:	Finished drilling out cement. Circulate. Displace w/brine water. Lay down drill pipe rubbers. Nipple down.		
9-9-89:	Jet and clean pits. Release rig at 8:00 PM MST on 9-9-	-89. WOCU.	
		Sep CAR ARE	
		RECE	
		OH AN 189	
SIGNED JONE	He foregoing is true and correct We will be and correct TITLE Sr. Production Clerk Title office use	DATE9-13-89	

*See Instructions on Reverse Side

APPROVED BY _______CONDITIONS OF APPROVAL, IF ANY:

SJS

DATE _