

YATES ENERGY CORPORATION
SIDEWINDER NO. 1
EDDY COUNTY, NEW MEXICO

SIDEWINDER DST SUMMARY

DST #1 8,455' - 8,530' (Cisco Canyon)

IHP	-	4109#
15 min. IFP	-	73#
90 min. ISID	-	1470#
120 min. FFP	-	98-171#
360 min. FSIP	-	3609#

Recovered: 583 feet of drilling fluid with very slight trace of distillate.

DST #2 5,265' - 5,380' (Straddle Pack) (Bone Springs)

IHP	-	2609#
10 min. IFP	-	70-100#
90 min. ISIP	-	1988#
30 min. 2FP	-	196-262#
90 min. 2SIP	-	1984#
120 min. 2SID	-	333-575#
360 min. FSIP	-	1984#

Recovered: 1130 feet sulfur water and 250' mud.

DST #3 9,860' - 10,030' (Straddle Pack) (Morrow)

MISRUN

DST #4 9,975' - 10,320' (Straddle Pack) (Morrow)

IHP	-	5047#
15 min. IFP	-	456-482#
90 min. ISIP	-	1205#
30 min. 2FP	-	426-448#
60 min. 2SIP	-	689#
180 min. FFP	-	458-619#
360 min. FSIP	-	1310#

Recovered: 1132 drilling mud.