Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89	
٠,	

DISTRICT I P.O. Box 1980, Hobbs, NM	88240
DICTRICT II	

OIL CONSERVATION DIVISION WELL

	Revised 1-1-89	υp
L API NO.		
0.015.06041		i

Santa Fe, New Mexico 87504-2088 Sindicate Type of Lease STATE FEE FEB 2 6 9 1 1 1 1 1 1 1 1 1	P.O. Box 1980, Hobbs, NM 88240	PO Box 208	RECEIVED	WELL AFINO.
DISTRICT III 1000 Rto Brazos Rd., Aziec, NM 87410 O. C. D. ARTENA, OFFICE SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OLL ORA OLL OLL		P.O. Box 2088 ECEIVED Santa Fe, New Mexico 87504-2088		30-015-26341 5. Indicate Type of Lesse
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OLL OAS WELL OTHER FUTURE SWD Pardue -C-, 8808 JV-P 8. Well No. 1 2. Name of Operator BTA 011 Producers 3. Address of Operator Unit Letter N : 176 Feet From The South Line and 1550 Feet From The West Line Section 11 Township 23S Range 28E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2996¹ GR 10. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ABANDONMENT PULL OR ALTER CASING OTHER: Plug Back	• •	'	LD C O 1941	STATE FEE XX
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:		ı		6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OIL OAS WELL OTHER FUTURE SWD Pardue -C-, 8808 JV-P 2. Name of Operator BTA 011 Producers 3. Address of Operator 104 S. Pecos, Midland, TX 79701 4. Well Location Unit Letter N: 176 Feet From The South Line and 1550 Feet From The West Line Section 11 Township 23S Range 28E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2996' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: Plug Back	SUNDRY NOTICE	S AND REPORTS ON WEL	LS	
OTHER Future SWD Pardue -C-, 8808 JV-P 2. Name of Operator BTA 0il Producers 3. Address of Operator 104 S. Pecos, Midland, TX 79701 4. Well Location Unit Letter N: 176 Feet From The South Line and 1550 Feet From The West Line Section 11 Township 23S Range 28E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2996 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: Plug Back	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		7. Lease Name or Unit Agreement Name	
3. Address of Operator 104 S. Pecos, Midland, TX 79701 4. Well Location Unit Letter N : 176 Feet From The South Line and 1550 Feet From The West Line Section 11 Township 23S Range 28E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2996 ' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Plug Back		oner Futur	e SWD	Pardue -C-, 8808 JV-P
3. Address of Operator 104 S. Pecos, Midland, TX 79701 4. Well Location Unit Letter N : 176 Feet From The South Line and 1550 Feet From The West Line Section 11 Township 23S Range 28E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2996 ' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: Plug Back	•			8. Well No.
104 S. Pecos, Midland, TX 79701 Well Location Unit Letter N : 176 Feet From The South Line and 1550 Feet From The West Line Section 11 Township 23S Range 28E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2996 ' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: Plug Back			_ ,	1 1
Well Location Unit Letter N : 176 Feet From The South Line and 1550 Feet From The West Line	•			
Unit Letter N : 176 Feet From The South Line and 1550 Feet From The West Line		79701	· ·	Undesignated Cherry Canyon
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2996	Unit Letter N: 176	000	200	711.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Plug Back		10. Elevation (Show whether 2996 GR	DF, RKB, RT, GR, etc.)	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Plug Back	11. Check Ap	propriate Box to Indicate 1		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Plug Back	NOTICE OF INTE	NTION TO:	SUE	SEQUENT REPORT OF:
PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: Plug Back	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERING CASING
OTHER: Plug Back	TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT
OTHER.	PULL OR ALTER CASING	_	CASING TEST AND C	
10 D. T. D. A. C. La J. C. Mine Wilson water all partinent details and give partinent dates including estimated date of starting any proposed	OTHER:		OTHER: Plu	ıg Back K
1) I DECENDA PERDECEN OT COMPLETA CENTERINA IL 1807IV SIGLE DU DETLIBERI DEDULS, DRU VIVE DELIBERS, DICHEURY ESPERANZA ENLE UN SELFUR UNA DECENDA	12 Describe Proposed or Completed Operation	os (Clearly state all pertinent details as	d give pertinent dates, inclu	uding estimated date of starting any proposed

work) SEE RULE 1103.

Killed well w/Brine Water 2-23-91

POH w/tbg.

Set CIBP @ 5915' w/wireline & capped w/35' cmt. New PBTD 5880', Filled csg w/brine.

SI - Pending SWD Hearing 3-21-91.

	nation above is the and outposite to the best of my knowled	ge and belief.	•	····
SIGNATURE	rother Nountton	mme Regulatory Administrator	_ DATE	2-25-91
TYPE OR PRINT NAME	Dorothy Houghton		TELEPHONE NO.	<u>915-682-3</u> 75
(This space for State Use)	ORIGINAL SIGNED BY MIKE WILLIAMS		MAR	6 199 1

-SUPERVISOR, DISTRICT IF CONDITIONS OF AFFROVAL, IF ANY:

Gariga H

.

C.D.O.

THE COMMENT SAME OF THE PROPERTY OF THE PROPER