

Form 3160-5

(This space for Federal or State office use)

UNITED STATES

FORM APPROVED				
Budget Bureau No.	1004-0135			
Expires: March	31, 1993			

(June 1990	DEPARTMENT	F THE INTERIOR	Budget Bureau No. 1004-0135 Expires: March 31, 1993
	BUREAU OF LAN	D MANAGEMENT	5. Lease Designation and Serial No. NM 62589
SUNDRY NOTICES AND REPORTS ON WELLS		6. If Indian, Allottee or Tribe Name	
Do no	ot use this form for proposals to crill or Use "APPLICATION FOR PE	r to deepen or reentry to a different reservoir. ERMIT—" for such proposals	The state of the s
		TRIPLICATE	7. If Unit or CA, Agreement Designation
I. Type o	il Gas —		
	of Operator Uther	A 1 4 7 3	8. Well Name and No. Federal 23 #3
	Pogo Producing Company	3 2 2 2	9. API Well No.
3. Address and Telephone No. P. O. Box 10340, Midland, TX 79702		30-015-21,400	
4. Locatio	on of Well (Footage, Sec., T., R., M., or Survey Descript		10. Field and Pool, or Exploratory Area
2310' FNL and 660' FEL of Section 23, T-22S, R-31E			Livingston Ridge Delaware 11. County or Parish, State
			Eddy County, NM
12.	CHECK APPROPRIATE BOX(s) T	O INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
	TYPE OF SUBMISSION	TYPE OF ACTION	
	Notice of Intent	Abandonment	Change of Plans
		Recompletion	New Construction
	XX Subsequent Report	Plugging Back	Non-Routine Fracturing
	Control About the state of the	Casing Repair	Water Shut-Off
	☐ Final Abandonment Notice	□ Altering Casing □ Other producing csg	Conversion to Injection
		Miner producting 639	Dispose Water (Note: Report results of multiple completion on Well
13. Describ	be Proposed or Completed Operations (Clearly state all pertin	nent details, and give pertinent dates, including estimated date of starting	Completion or Recompletion Report and Log form.)
gi	ve subsurface locations and measured and true vertical dep	oths for all markers and zones pertinent to this work.)*	and the control of th
Dwill	lod 7 7/0" hole to 04001 T.D.	manched 7/16/01 logged way 102	
+ 174	# csa GS 8409 FC 8362 etam	. reached 7/16/91, logged, ran 193 e tool @ 6205, Western cmt'd 1st st	JOINTS 5 ½ 15.5#
15.6	PPa. plua dn 1650 PSI 06:35	7-18-91, open stage tool, circ 115	ske cont to nit
cmt'	d 2nd stage w/ 635 sks PSL "H	" 12.4 PPg, tailed w/ 100 sks "H",	plug dn w/ 3000#.
tool	held (ok)	g, in the in, less than in ,	p. 123 4.1. 11, 3000 11,
			Aug.
			. 1 - 2
			in
			M 10 S G3A130
			B: G
			တ်ကို 💆
14. I heret	by certify that the folegoing is the and correct	11	

Approved by _______ Conditions of approval, if any:

Title

Div. Operations Supervisor

Date