Submit 3 Copies to Appropriate District Office	En,	State of New Minerals and Natur		artment			Form C-103 Revised 1-1-89
<u>DIŞTRIÇT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL (CONSERVA		ION	WELL API NO.		
2040 Pacheco St. Santa Fe, NM 87505					30-015-26406 Indicate Type of Lease		
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410					•State Oil & Gas L	STATE	FEE
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-191) FOR SUCH PROPOSALS.)					7Lease Name or Unit Agreement Name		
Type of Well: Oll GAS WELL X WELL		OTHER		••••••••••••••••••••••••••••••••••••••	002337 Pardue -D-, 88	08 JV-P	
aName of Operator BTA OIL PRODUCERS	OGRID	No. 003002			⊮Well No. 2		
Address of Operator	D. T.X. 79701		<u> </u>		Pool name or Wil		
+Well Location			<u> </u>		Loving, East	(Brushy Canyo	on)
Unit Letter D : 990	Feet From Th	e North	Line and	660	Feet From Th	ne Wes	tLine
Section 11	Tottilon	ip 23S Elevation (<i>Show whether</i>	Range	28E	NMPM	Eddy	County
	INTENTIOI	AND ABANDON		SUBS	SEQUENT F		
	INTENTIOI] Plug] chan]	N TO: and abandon [ige plans [REMEDIAL WO COMMENCE D CASING TEST	SUBS DRK RILLING OF AND CEME Littional U	SEQUENT F	REPORT O ALTERING (PLUG AND A Nyon 'B' Sand	CASING INBANDONMENT
ERFORM REMEDIAL WORK	INTENTIOI PLUG CHAN C	N TO: AND ABANDON IGE PLANS all pertinent details, and w/ rocts & tbg ling due to very hard s ble w/ 2% KCL wtr, tst Perf w/ 4" csg guns (620', RU swb & made , 400' entry overnight, containing 63 ball set wabbing & testing	REMEDIAL WO COMMENCE D CASING TEST. OTHER: Add of give pertinent dates, if sand, POH w/ Hydro plug to 1000 psi, rai 5 stars, swb dry, rec 1 8W w/ clicht	SUBS ORK RILLING OF AND CEME Ittional Up notucting est static baile set bg 2 jts 25 - 5835'	SEQUENT F	REPORT O ALTERING O PLUG AND A nyon 'B' Sand ing any proposed	CASING INBANDONMENT
Check NOTICE OF PERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING DTHER: DDEscribe Proposed or Completed Opera work) SEE RULE 1103. 03/23/00 TD 6,250' PB 6,165' M 03/24/00 RIH tag SN@5983'. B pkr w/ bullplug) set plug acetic acid, POH w/ tbg, JSPF, POH. Set Baker 03/25/00 Open well 0 psi, RIH w/ follows: A/ w/ 1000 gals 38,500 #'s of sand 03/26/00 Open well, well on vac, 03/30/00 RIH w/ Prod equipment 04/04/00 Pmp 24 hrs, rec. 10 BO	INTENTIOI PLUG CHAN C	N TO: AND ABANDON IGE PLANS <i>all pertinent details, and</i> w/ rocts & tbg ling due to very hard s we w/ 2% KCL wtr, tst Perf w/ 4" csg guns (620', RU swb & made , 400' entry overnight, containing 63 ball sea wabbing & testing	REMEDIAL WO COMMENCE D CASING TEST. OTHER: Add d give pertinent dates, in sand, POH w/ Hydro plug to 1000 psi, rai \$5,815' - 5819'; 5,8 \$5 runs, swb dry, rec 1 BW w/ slight f alers. Frac well w/ 1	SUBS ORK RILLING OF AND CEME litional U/ nclucting est static baik se tbg 2 jts 25 - 5835' tr oil. RU I 5,200 gals	SEQUENT F	REPORT O ALTERING (PLUG AND A nyon 'B' Sand ing any proposed kc-set % // 4 // 234 // // / / / / / / / / / / / / / / / /	CASING INBANDONMENT
Check NOTICE OF PERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING DTHER: DESCRIBE Proposed or Completed Opera work) SEE RULE 1103. 03/23/00 TD 6,250' PB 6,165' M 03/24/00 RIH tag SN@5983'. B pkr w/ bullplug) set plug acetic acid, POH w/ tbg, JSPF, POH. Set Baker 03/25/00 Open well 0 psi, RIH w/ follows: A/ w/ 1000 gals 38,500 #'s of sand 03/26/00 Open well, well on vac, 03/30/00 RIH w/ Prod equipment 04/04/00 Pmp 24 hrs, rec. 10 BO	INTENTIOI PLUG CHAN C	N TO: AND ABANDON IGE PLANS <i>all pertinent details, and</i> w/ rocts & tbg ling due to very hard s we w/ 2% KCL wtr, tst Perf w/ 4" csg guns (620', RU swb & made , 400' entry overnight, containing 63 ball sea wabbing & testing	REMEDIAL WO COMMENCE D CASING TEST. OTHER: Add d give pertinent dates, in sand, POH w/ Hydro plug to 1000 psi, rai \$5,815' - 5819'; 5,8 5 runs, swb dry, rec 1 BW w/ slight f alers. Frac well w/ 1	SUBS ORK RILLING OF AND CEME litional U/ nclucting est static baik se tbg 2 jts 25 - 5835' tr oil. RU I 5,200 gals	SEQUENT F	ALTERING O ALTERING O PLUG AND A nyon 'B' Sand ing any proposed AC-set % AP OCD - AP AP OCD - AP	CASING INBANDONMENT

CONDITIONS OF APPROVAL, IF ANY: