Submit 3 Copies to Appropriate District Office

1. Type of Well: WELL X

2. Name of Operator

3. Address of Operator

Section

CONDITIONS OF APPROVAL, IF ANY:

4. Well Location

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-1	03
Revised 1	1-59

Line

County

DISTRIC	TI			
P.O. Box	1980.	Hobbs,	NM	88240

OIL CONSERVATION DIVISION P.O. Box 2088

23**-**S

Township

WELL API NO. 30-015-26455

DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088

5. Indicate Type of Lease FEE X STATE

1000 Rio Brazos Rd., Aztec, NM 87410

Oryx Energy Company /

10

P.O. Box 1861, Midland, Texas 79702

6. State Oil & Gas Lease No. 12 '91 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" 7. Lease Name or Unit Agreement Name MERESAN, OFFICE (FORM C-101) FOR SUCH PROPOSALS.) Lewis Estate 8. Well No. 9. Pool name or Wildcat Loving, East-Delaware : 1880 Feet From The South

_ Feet From The _ East

Eddv

NMPM

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2976.4' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB X OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

Range

Line and 660

28-E

- work) SEE RULE 1103. 9-11-90 Spudded 11" hole @ 3:00p.m. Ran & CMT'D 13 JTS 8 5/8", 24#, STC CSG to 515'. CMT'D w/400 SXS "C" CMT + 2% CaCl₂ + 1/4 PPS Flakes. Circ'd 182 SXS to pits.
- WOC 12 hrs.
- 9-24-90 Ran 15 JTS 5 1/2", 15.5#, K-55, STC CSG + 138 JTS 5 1/2", 14#, J55, STC CSG. CS @ 6241'. CMT'D w/650 SXS 50/50 POZ "H" w/2% gel + 10% salt + 4% Halad-9+.3% CFR-3, followed by 150 SXS "H" + 10% salt, mixed @ 8 BPM, 400 PSI, displaced w/75 bbls FW + 75 bbls mud. Bumped plug to 1800 PSI. Drop bomb open DV tool, Circ'd 5 hrs. returned 100 SXS CMT to pit. CMT'D thru DV tool w/800 SXS Howco Lite "H" + 10% salt + 1/4 PPS flocele followed by 100 SXS "H" + 2%, CaCl2. Circ'd 88 SXS to pit. Bumped plug, closed DV tool to 2200 PSI. WOC 4 days.

I hereby certify that the informa	tion above is true, and complete to the best of my knowle	ndge and belief.	
SIGNATURE	in I Time	me Proration Analyst	_ DATE 10-12-90
TYPE OR PRINT NAME MA	ria L. Perez		TELEPHONE NO. 915/688-0375
· · · · · · · · · · · · · · · · · · ·	PRIGINAL SIGNED BY		UCT 1 8 1940 0
	UPERVISOR, DISTRICT IL	mu	— DATE ————