
Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural R ources Department



- DATE -

DISTRICT I P.C. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION

F.C. BOX 1980, HOODE, NM 88240	P.O. Box 2088 ECE Santa Fe, New Mexico 87504-2088		30-015-26460
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexic		87504-2088	5. Indicate Type of Lease
DISTRICT III	lv .	1AY - 6 1991	STATE FEE X
1000 Rio Brazos Rd., Aziec, NM 87410		O. C. D.	6. State Oil & Gas Lease No.
SUNDRY NOTICE	S AND REPORTS ON WELL	LS OFFICE	
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN IR. USE "APPLICATION FOR PER	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	3001	
1. Type of Well: OLL GAS WELL Y WELL			
WELL Y WELL 2. Name of Operator	OTHER		Pardue Farms
Oryx Energy Company /			8. Well No.
3. Address of Operator			9. Pool name or Wildcat
P. O. Box 1861, Mida	lnd, TX 79702		Loving, East Delaware
Unit Letter H: 1950	Town North	661	0
Onit Letter : _1980	Peet Prom the 100 cm	Line andO	O Feet From The East Line
Section 10	Township 23-S Ra	nge 28-E 1	NMPM Eddy County
	10. Elevation (Show whether	· · · · · · · · · · · · · · · · · · ·	
11. Check App	2998.8'		
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
	TION 10.	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB	
OTHER: Sqz. perfs, re-perf	& frac X	OTHER:	
 Describe Proposed or Completed Operations work) SEE RULE 1103. 	i (Clearly state all pertinent details, an	d give pertinent dates, includ	ling estimated date of starting any proposed
1) MIRU PU. POH N	N/ RODS & PUMP. ND	WH & NU BOP.	TOH W/ 2-7/8" TBG & PSU.
2) TIH W/ 4-3/4" R PBTD 6250'. TOH	RB & 6 - 3-1/2" DC'S N W/ TBG & TOOLS.	S ON 2-7/8" TBG	G. DO CIBP @ 6131 & CO TO
3) TIH W/ 5-1/2" R	TTS PKR ON 2-7/8" TE	G & SET @ 6125	'. EIR INTO PERFS 6137-60'
& VERIFY CHANNE	L 10 PERFS 60/2-6115	' BY MONITORING	ANNULUS. RAISE & SET PKR
4) SQZ BRUSHY CANYO PRESS UP ON SQZ.	ON W/ 100 SX CLASS C SI WELL OVERNITE &	NEAT. RLS PKR WOC. TOH W/ T	, REV OUT EXCESS, SET PKR & BG & PKR.
	(Cont. Page 2)		
I hereby certify that the information above is true and	complete to the best of my knowledge and	belief.	
SIGNATURE Masia Z. F.	<u> πη</u>	Proration Ana	alyst
TYPEORPRINTINAME Maria L. Pe	rez		TELEPHONE NO. 915/688-03
(This space for State Use) ORIGINAL S	GNED BY		
MIKE WILLIA			MAY _ 7 1991
	S SISTEMAT IN		・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・

APPROVED BY SUPERVISOR, DISTRICT 15 CONDITIONS OF APPROVAL, IF ANY: