	DEPAR BUR	UNITED STATES RTME OF THE I EAU OF LAND MANAC	NTERIOR	SUBMIT IN TRIPLICATE (Other instruction on reverse side)	Expires August 31, 1-85  5. LEASE DISIGNATION AND SECIAL NO C  NM 83032
(Do not use this	NDRY NO	OTICES AND REPC	DRTS ON		6 IP INDIAN, ALLOTTEE OR TEINE NAME
OIL CAS	Х отне	R			7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR				JAN 11 '91	8. FARM OR LEASE NAME
Yates Energy 3. ADDRESS OF GPREATO	7 Corpora	ation \( \square \)			Texasville Federal Com
4. Location of Well ( See also space 17 be	Report location	ell, New Mexico &	88202-232; with acy State	C. C. D.  Requirements. OFFICE	1 10. FIELD AND POOL, OR WILDCAT
2310' FSL & 1650' FWL					Bandana Point - Strawn 11. SEC., T., E., M., OR BLE. AND BURVEY OR ARKA
					Section 27-23S-23E
14. PERMIT NO.		15. ELEVATIONS (Show s	bether DF, RT, G	, etc.)	12. COUNTY OF PARISE 13. STATE
30-015-26501		1 4188.1 GR	I h	()	Eddy NM
	NOTICE OF IN	Appropriate Box To Inc	Sicole Nature I		
TEST WATER SHUT-	<u></u>	PULL OR ALTER CASING		WATER SHUT-OFF	EINT REPORT OF:
FRACTURE TREAT		MUNTIPLE COMPLETE		PRACTURE TREATMENT	ALTIRING CARING
SHOOT OR ACIDIZE  REPAIR WELL		ABANDON® CHANGE PLANE		SHOOTING OR ACIDIZING	ABANDONMENT®
(Other)	لــا	CHANGE FLANS		(Other) (Norm: Report result	s of multiple completion on Well pletion Report and Log form.)
17. DESCRIBE PROPOSED O proposed work. I	R COMPLETED f well is dire	OPERATIONS (Clearly state all ectionally drilled, give subsur	pertinent deta	ils, and give pertinent dates nd measured and true vertic	s, including estimated date of starting any cal depths for all markers and some perti-
· · · · · · · · · · · · · · · · · · ·					t., btm. @ 8723' K.B.
Pmpd. 200	O gals. :	Xylene & 200 gals KCL. Circ. 250 g	. 15% aci	d 2/inhibitor, re	versed to pit. Dis-
K.B. Pe Ran in ho Pmpd. dov	rforated ole w/pk wn csg. v isplaced	Strawn Lime at 8 r. and 268 jts. (w/5 bbls. wtr. to	639' - 86 8543.78') reverse nto forma	57' K.B. w/57 .38 2 3/8" J-55 tbg. acid into tbg. Se	. Found TOC @ 6326' " dia. holes (2 SPF). , set @ 8576.48' K.B. t pkr. w/5000# tension. @ 2600 - 3000 psig.
Slowly di					
Slowly di				,	Dec Añ
Slowly di				,	R Dec 27 ARE
Slowly di					REC 27 _
Slowly di					REC
Slowly di				;	RECEIVE
Slowly di				:	REC
Slowly di				:	RECEIVE
Slowly di Pressure	the forego⊊	8 true and correct		:	RECEIVE
Slowly di	the foregot	To true and correct	<sub>LE</sub> Land	; man	RECEIVE