Submit 3 Copies to Appropriate District Office

State of New Mexico En. , Minerals and Natural Resources Department

Form C-103	
Revised 1-1-89	

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-26704

6. State Oil & Gas Lease No.

5. Indicate Type of Lease

FEE XX STATE

_	<u></u>	SUNDRY NOTICE	S AND REPORTS ON V	WELLS						
•	DO NOT USE THI	S FORM FOR PROPO DIFFERENT RESERVO	SALS TO DRILL OR TO DEE! IR. USE "APPLICATION FOR) FOR SUCH PROPOSALS.)	PEN OR PLU PERMIT	jg back I <mark>ECEIVI</mark>	-	7. Leas	e Name or Unit A	greement Name	
•	Type of Well: Off. X	WELL [OTHER	AL	JG 15	1991	Nyt	neyer "A"		
_	Name of Operator	alty, Ltd.			O. C.		8. Well 2			-
L.	Address of Operati	or	550 Dallas, TX		(IESIN, V	J. 7. 1. C. J		name or Wildcat st Loving	(Delaware)	
L	Well Location		Feet From The North		Line and _	2310		Feet From The	West	Line
	Section	15	Township 23S	Range	28E		MPM	Eddy	(County
			10. Elevation (Show when 2999 GR	ther DF, RKB), RT, GR,	etc.) 				
_		Charle As	propriete Boy to Indica	ite Nature	of Not	ice. Re	nort. o	r Other Data	ı	

Onit Lew	·									
Section	15	Township	23S		TIKE.		NMPM	Eddy	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	County
		10. EI	evation (Show 2999 G		DF, RKB, K	T, GR, etc.)				
		opropriate l			Vature of	f Notice R	enort of	r Other	Data	
11.				iicaie i	laime of				EPORT OF:	
ı	NOTICE OF INTE	NIION I	J .				OLGO	_,,,,	-	
PERFORM REME	DIAL WORK	PLUG AND	ABANDON		REMEDI	AL WORK			ALTERING CASI	NG
TEMPORARILY A	BANDON	CHANGE I	PLANS		COMME	NCE DRILLING	OPNS.		PLUG AND ABAN	NDONMENT
PULL OR ALTER	CASING				CASING	TEST AND CE	EMENT JO	в		
OTHER: Frac	Bone Springs			x	OTHER:	Perfo	rate			
work) SEE RU						•				æď
7-23-91	Set 5-1/2" cs w/ 570 sx Cla Western cmt t and 8% salt f	ss "C" c hrough D	ontainin V tool w	ig 4#/ i/ 570	sk sal sx Cl	t and 5% ass "C"	cello	phane	flakes.	
8-03-91	Pressure test	DV tool	to 3600) psi.	Held	ok.				
8-07-91	After DO csg	to 6360'	(PBTD),	pres	ssure t	ested cs	g to 3	600 ps	si. Held o	k.
8-08-91	Perforate Bor	ne Spring	s 6257 '	- 628	38' w/	64 holes	and a	cidize	· .	6
	ly – testing Bo									
Intentio	ons - fracture	treat Bo	ne Sprin	igs W	/ 21,00	0 gallon	s and	52,500)# sand.	·
I hereby certify that	the information above is true a	and complete to the	best of my know	whodge and	belief.					
	aucs.			171	Seni	or Petro	leum E	ngine	$\frac{er}{214}$ DATE $\frac{8/13}{(214)}$	/91
TYPE OR PRINT NA	$\langle a \rangle = \langle a \rangle = \langle a \rangle$	zemore							(214 TELEPHONE NO.	•)

(This space for State Use)ORIGINAL SIGNED BY

MIKE WILLIAMS

SUPERVISOR, DISTRICT IT

AUG 2 3 1991

- DATE -

CONDITIONS OF AFFROVAL, IF ANY:

APTROVED BY -