

Submit to Appropriate
District Office
State Lease - 6 copies
Fee Lease - 5 copies

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-101
Revised 1-1-89

CIBP
OP

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

AUG 13 1992

O. C. D.
ARTESIA OFFICE

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

API NO. (assigned by OCD on New Wells)

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK

1a. Type of Work:

DRILL ☐

RE-ENTER ☐

DEEPEN ☐

PLUG BACK ☒

b. Type of Well:

OIL

WELL ☒

GAS

WELL ☐

OTHER ☐

SINGLE
ZONE ☐

MULTIPLE
ZONE ☐

7. Lease Name or Unit Agreement Name

Pardue Farms 27

8. Well No.

9

9. Pool name or Wildcat

East Loving Delaware

4. Well Location

Unit Letter G : 2080 Feet From The East Line and 1880 Feet From The North Line
Section 27 Township 23S Range 28E NMPM Eddy County

10. Proposed Depth
6256'

11. Formation
Brushy Canyon

12. Rotary or C.T.
-

13. Elevations (Show whether DF, RT, GR, etc.)
3044 GR

14. Kind & Status Plug Bond
Blanket Bond

15. Drilling Contractor
NA

16. Approx. Date Work will start
ASAP

17.

PROPOSED CASING AND CEMENT PROGRAM

SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
12-1/4"	8-5/8"	24	500	475	Surface
7-7/8"	4 1/2"	11.6	6800	875	2300'

Set CIBP @6256' to correctly plug back from the Bone Springs.
See attached.

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: IF PROPOSAL IS TO DEEPEN OR PLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUCTIVE ZONE. GIVE BLOWOUT PREVENTER PROGRAM, IF ANY.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randy R. Johnson TITLE Sr. Operations Engineer DATE 8-12-92

TYPE OR PRINT NAME Randy R. Johnson

TELEPHONE NO. 915 683 476

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE AUG 17 1992

CONDITIONS OF APPROVAL, IF ANY:

PARDUE FARMS "27" #9

6200

OCD TOP OF BONE SPRINGS

Proposed CIBP to be set 8-28-92 to plug back Bone springs.

PPDC TOP OF BONE SPRINGS

6300

CIBP set @ 6290' 11-13-91. Dr1'd out CIBP and CO to 6713' (new PBD) 7-28-92. POB 7-30-92 to pap test Bone Springs w/ Brushy Canyon.

6400

PARDUE FARMS "27" #9

6200

OCD TOP OF BONE SPRINGS

Proposed CIBP to be set 8-28-92 to plug back Bone springs.

PPDC TOP OF BONE SPRINGS

6300

CIBP set @ 6290' 11-13-91. Drl'd out CIBP and CO to 6713' (new PBD) 7-28-92. POB 7-30-92 to pmp test Bone Springs w/ Brushy Canyon.

6400

PARDUE FARMS "27" #9

6200

OCD TOP OF BONE SPRINGS

Proposed CIBP to be set 8-28-92 to plug back Bone springs.

PPDC TOP OF BONE SPRINGS

CIBP set @ 6290' 11-13-91. Dri'd out CIBP and CO to 6713' (new PBTB) 7-28-92. POB 7-30-92 to pmp test Bone Springs w/ Brushy Canyon.

6300

6400