AEDEIVED

RELEIVEL

•03		
	ITED STATES APR 2 8 1993	FORM APPROVED Budget Bureau No. 1004-0135
(June 1990) W W DEPARTME	NT OF THE INTERIOR	Expires: March 31, 1993
BUREAU OF	LAND MANAGEMENTO, C. D.	5. Lease Designation and Serial No. NM51073
SUNDRY NOTICES	S AND REPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
	rill or to deepen or reentry to a different reservoir	•
Use "APPLICATION FO	DR PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
I. Type of Well Oil Gas Well Well Other		8. Well Name and No.
L J Well L J Other 2. Name of Operator		Muley Federal Mo-1
Collins & Ware, Inc.		9. API Well No.
3. Address and Telephone No.		300-152-69750
	and, Texas 79701 (915) 687-3435	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Dark Canyon-Upper Penn
1/001 -01 6 1/501 777 6 0	0.6 m 0.2 d p 0.5 H	11. County or Parish, State
1433' FSL & 1459' FEL of Sec.	26, 1-23-5, K-23-E	Eddy, New Mexico
12. CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPO	
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment Recompletion	Change of Plans New Construction
· Subsequent Report	Recompletion K Plugging Back	Non-Routine Fracturing
Country of the countr	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state a	Il pertinent details, and give pertinent dates, including estimated date of starting depths for all markers and zones pertinent to this work.)*	ng any proposed work. If well is directionally drilled
give substitute focations and incastron and true vertice	and depois for all indirects and zeroes permitting one workly	
	,	
Run and set a CIBP a	t appx. 9,550' KB. Dump 35' cement on CIBP.	
Run and set a CIBP at	t appx. 8,600' KB. Dump 35' cement on CIBP.	
Note: BLM will r	equire a 200' cement plug at top of Bone Spring	prior to final P/A.
Perforate Delaware fr	om 4,867' to 4,895' KB.	
Acidize and/or fractu		
	wn hole equipment; initiate production.	
instail stillace and do	wh hore equipment, intrace production.	
14. I hereby certify that the foregoing is true and correct		
Ollow of Class	Title Agent for Collins & Ware, In	nc, Date 3/30/93
(This space for Federal or State office use)	PETROLFUL! ENGINEER	
भारतकरूत हो अपने इत्याम इयावासक्षेत्र	1961	Date 4/25/93
Approved by Conditions of approval, if any:	Title	Date