

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

dst
dp

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JUN 29 1992

O. C. D.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO.
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Parker & Parsley Development Company		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 3178, Midland, Texas 79702		7. Lease Name or Unit Agreement Name Pardue Farms 27
4. Well Location Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>785</u> Feet From The <u>East</u> Line Section <u>27</u> Township <u>23S</u> Range <u>28E</u> NMPM <u>Eddy</u> County		8. Well No. 10
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3034 GR		9. Pool name or Wildcat S. Culebra Bluff

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/22/92 - 6/23/92 TIH w/ logging tools. Tag bridge @ 707'. POH w/ tools. Wash & ream to 1600'. TIH w/ logging tools. Tag bridge @ 600'. Terminated logging operations. TOH w/ logging tools. TIH, wash & ream to btm. Circ & cond mud. Ran 151 jts 5-1/2" 15.5 & 17#, J-55, LTC csg. Set csg @ 6795' (DVT @ 5723'). Cmt 1st stage w/ 275 sx D-S Self Stress + 1/4# per sx D29 Cellophane. Cmt 2nd stage w/ 475 sx Class "C" Lite & 350 sx Class "H" Self Stress. Plug dwn @ 1:15 pm 6/23/92. WOC 12 hrs. ND BOP, cut off csg., install tbh head. Released rig 6/23/92. W.O. completion.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randy R. Johnson TITLE Sr. Operations Engineer DATE June 25, 1992
TYPE OR PRINT NAME Randy R. Johnson TELEPHONE NO. 683-4768

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT I

APPROVED BY _____ TITLE _____ DATE JUL 17 1992

CONDITIONS OF APPROVAL, IF ANY: