

Pinnacle State #3
Continued

12/1/93 - continued

TLTR 56 bbls. Flow well bk. 1 bbl. RU & start swbg. well swbd dn in 4/runs
Rec 20 bbls, Make 1 run/Hr-4 hrs rec 4 bbl, POOH w/pkr. PU notched collar
& RIH to 3406. Prep to frac.

12/2/93 RU Cardinal Svy, Run base log. Bleed press of well small amt of gas. RU
Dowell to frac. Perfs @ 3637-43 dn 2-7/8" tbg open ended @ 3406.

12/3/93 Flow well to test tank.

12/4/93 Rig to flowline. Run tbg below perfs, no fill, Perfs @ 3637-43, POOH
w/2-7/8" tbg, PU 25' MA, 4' Perf sub, sn & RIH to 3540' SN. RIH w/
2-1/2 X 1-1/2" x 20' Pump w/16' Gas anchor. Seat pump & Hang well
on. Rel Rig. Start well pumping.