

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-27092
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	VB-0142

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/>	7. Lease Name or Unit Agreement Name H. Buck State
2. Name of Operator Pogo Producing Company	8. Well No. 1
3. Address of Operator P. O. Box 10340, Midland, TX 79702-7340	9. Pool name or Wildcat Wildcat Bone Springs
4. Well Location Unit Letter <u>J</u> : <u>1982</u> Feet From The <u>South</u> Line and <u>1961</u> Feet From The <u>East</u> Line Section <u>16</u> Township <u>24S</u> Range <u>29E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2914' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Pull isolation pkrs & set RBP ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

APR 24 1996

4/11/96 POOH w/ isolation packers @ 7504' & 5100'

4/12/96 Set RBP @ 7510' to isolate Bone Springs from the Delaware. Also set RBP @ 5510' on order to pump just the upper Delaware. Run production tubing, rods & pump. Put well on production

Well pumping from upper Delaware.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Barrett L. Smith TITLE Senior Operations Engineer DATE 4/22/96
TYPE OR PRINT NAME Barrett L. Smith (915)682-6822 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE APR 29 1996

CONDITIONS OF APPROVAL, IF ANY: