Lambchop 20 Fed Com No. 1 Plugging Procedure

6. Spot 25 sx Cl "C" Neat plug at 550'.

- ----

7. Cut off wellhead below ground level. Put 10' cement plug in top of well and install dry hole marker. Clean location.

Anticipated start date is May 17, 1993.

+	- State of Muse N	-	clst	
Submit 3 Copies to Appropriate District Office	State of New Mexico ELergy, Minerals and Natural Resources Department		Form C-103	
DISTRICT I P.O. Box 1980, Hobba, NM 88240	OIL CONSERVATION DIVISION		· · · · · · · · · · · · · · · · · · ·	
P.O. Box 2088		88	WELL API NO.	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 575512088		30-015-27220		
		5. Indicate Type of Lease STATE FEE X		
		6. State Oil & Gas Lease No.		
O.C.D.				
SUNDRY NOTICES AND REPORTS ON WELLS FOR F ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name		
1. Type of Well: OIL CAS WELL XX WELL	OTHER	· · · · · · · · · · · · · · · · · · ·	Lambchop 20 Fed Com	
2. Name of Operator			8. Well No.	
Santa Fe Energy Operating Partners, L.P. 3. Address of Operator			a. well No. 1	
550 W. Texas, Suite 1330, Midland, Texas 79701			9. Pool name or Wildcat	
The second of			Undesignated Delaware	
Unit LetterB :479 Feet From TheNorthLine and1814 Feet From TheEastLine				
Section 20	Township 24S P	unge 25E	MPM Eddy Court	
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	IMPM Eddy County	
4137.9' GR				
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O				
OTHER:				
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
Depth 10,400' (TD). Evaluation of logs and DST indicates Strawn formation is not commercial. Plan to attempt a Delaware oil completion.				
2-12-93: Plugging back to Delaware. Set first plug at 10,383' w/ 42 sx Cl H.				
2-13-93: Set 2nd plug at 9770' w/ 42 sx Cl H. Set 3rd plug at 8560' w/ 42 sx Cl H. Set 4th plug at 6770' w/ 200 sx Cl H. Dress off plug to <b>p</b> at 6308'. Good cement at 6345'. Prep to rup 5 1/2"				
casing.				
2-14-93: Ran 130 jts 5-1/2" 17# K-55 LT&C casing and set at 5806'. FC @ 5714'.				
oomeneed w/oor	J SA ILEMINI PHIS CONFS	ining Q#/ab C+1		
	and 2.4#/sk KCl. Set slips w/105,000#. Cut off 5-1/2" and weld on bell nipple. Rig Released at 4:00 p.m. CST. WOCU.			
Kig I		ST. WOCU.		
I hereby service that the information above is true and complete to the best of my geowiedge and belief.				
SKONATURE FILLY Feb. 15, 1993				
TYPE OR PRINT NAME TErry McCullough			915/	
			TELEPHONE NO. 687-3551	
(This space for State Use) ORIGINAL SIGNED BY MIKE WILLIAMS				
SUPERVIS			Fa8 1 8 1993	
APPROVED BY SUPERVISOR, DISTRICT 19 TITLE			DATE	