

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division

811 S. 1st Street

Artesia, NM 88210-2834

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Pogo Producing Company

3. Address and Telephone No.

P. O. Box 10340, Midland, TX 79702-7340

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FSL & 990' FEL, Section 28, T23S, R31E

5. Lease Designation and Serial No.

NM-40659

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Pure Gold D #16

9. API Well No.

30-015-27497

10. Field and Pool, or Exploratory Area

Sand Dunes W. Del.

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☒ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 2/29/96 Set RBP @ 7587'. Perf Delaware 7372'-86', (28 - .50" dia holes). Acidize w/ 1000 gals 7-1/2% HCl. Swab test well.
- 3/2/96 Frac Delaware w/ 26720# 20/40 sand. Flow well back.
- 3/3/96 Circulate hole clean. Swab test well.
- 3/4/96 Latch onto RBP @ 7587' & POOH.
- 3/5/96 Run production equipment. Put well on production. All open Delaware zones combined.

ACCEPTED FOR RECORD

AUG 01 1996

14. I hereby certify that the foregoing is true and correct

Signed

Title

Senior Operations Engineer

Date

7/29/96

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: