

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of well

☒ Oil ☐ Gas ☐ Other

2. Name of Operator

CHEVRON U.S.A. INC. ATTN: NITA RICE

3. Address and Telephone No.

P. O. BOX 1150
MIDLAND, TEXAS 79702

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UNIT L, 2546' FSL & 900' FWL
SEC 1, T-23S, R28E

5. Lease Designation and Serial No.

NM-18038

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

LENTINI "1" FEDERAL #9

9. API Well No.

30-015-27569

10. Field and Pool, or Exploratory Area

HERRADURA BEND EAST

11. County or Parish, State

EDDY, NM

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

12 TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other NEW WELL COMP

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimate date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

COMPLETION WORK BEGAN 06/23/94. LOG GR/CCL F/6270'-5500'. DUMP 90 GALS OF 15% ACID ACROSS PERF ZONE. PERF F/6124'-6138'. DUMP 90 GALS OF 15% HCL ACROSS PERFS. FRAC PERFS W/9,100 GALS WTR GEL 40 W/16,300# 16/30 MESH BRADY SD & 3,000# SUPER LC RESIN COATED SD. MIRU, ND VALVE, NU BOP. C/O SD F/5580'-6020', CIRC HOLE CLEAN. SPOT 1000 GALS 15% HCL ACID. PERF F/5897'-5918'. FRAC PERFS W/21,000 GALS WTR GEL 40 WITH 55,200# OF 16/30 MESH BRADY SD. ND VALVE, NU BOP. CLEAN OUT SD F/5921'-6270'. CIRC HOLE CLEAN. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 06/30/94.

OPERATOR:

PLEASE SUBMIT SUNDRY NOTICE FOR SPUDDING
THE WELL AND RUNNING AND CEMENTING
THE CASINGS.

14. I hereby certify that the foregoing is true and correct

Signed Nita Rice Title

TECHNICAL ASSISTANT

Date 7/6/94

(This space for Federal or State office use)

Approved by _____ Title

Date _____

Conditions of approval, if any: