

LINE	RATE 1		RATE 2		RATE 3		RATE 4		Pc2/(Pc2-Pw2) =	
	'1ST	'2ND	'1ST	'2ND	'1ST	'2ND	'1ST	'2ND		
1 QM	1.983	1.983	1.671	1.671	1.234	1.234	0.618	0.618		1.091
2 TW	534	534	534	534	534	534	534	534	[Pc2/Pc2-Pw2]n =	1.119
3 Ts	658.0	658.0	658.0	658.0	658.0	658.0	658.0	658.0		1.227
4 T	596.0	596.0	596.0	596.0	596.0	596.0	596.0	596.0		1.538
PR (est)	0.88		1.09		1.54		2.16			
5 Z(est)	0.920	0.905	0.908	0.895	0.885	0.872	0.859	0.848		
6 TZ	548.2	539.6	541.1	533.4	527.3	520.0	511.9	505.5	AOF= Q	2.164
7 GH/TZ	14.243	14.470	14.430	14.637	14.807	15.016	15.252	15.446		1.870
8 eS	1.706	1.721	1.718	1.731	1.742	1.756	1.772	1.785		1.515
9 l-e-S	0.414	0.419	0.418	0.422	0.426	0.431	0.436	0.440		0.950
10 Pt	593.2	593.2	733.2	733.2	1033.2	1033.2	1453.2	1453.2		
11 Pt2 /1000	351.9	351.9	537.6	537.6	1067.5	1067.5	2111.8	2111.8		
12 Fr	0.018112	0.018112	0.018112	0.018112	0.018112	0.018112	0.018112	0.0181123		
13 Fc:FrTZ	9.929	9.773	9.801	9.661	9.551	9.418	9.272	9.156		
14 FcQm	19.69	19.38	16.38	16.14	11.79	11.62	5.73	5.66		
15 L/H(FcQm)	387.6	375.6	268.2	260.6	138.9	135.1	32.8	32.0		
16 Fw	160.4144	157.2936	112.0802	110.0985	59.18403	58.15023	14.30245	14.076641		
17 Pw2	512.3	509.2	649.7	647.7	1126.7	1125.7	2126.1	2125.9		
18 Ps2	874.0	876.1	1116.1	1121.4	1963.1	1976.8	3766.8	3793.9		
19 Ps	934.9	936.0	1056.4	1058.9	1401.1	1406.0	1940.8	1947.8		
20 P	764.0	764.6	894.8	896.1	1217.2	1219.6	1697.0	1700.5		
21 Pr	1.14	1.14	1.33	1.33	1.81	1.81	2.53	2.53		
22 Tr	1.68	1.68	1.68	1.68	1.68	1.68	1.68	1.68		
23 Z	0.905	0.905	0.895	0.895	0.872	0.872	0.848	0.848	FORM C122-D	