### 3,000 pel Working Pressure

#### 3 MWP

### STACK REQUIREMENTS

No.	Nem		Min. I.D.	Min. Nominal
1	Flowline			
2	Fill up line	<del></del>	7	2"
7	Drilling nipple		<del>                                     </del>	
4	Annular preventer		1	
5	Two single or one dual hydraulically operated rams			
6a	Drilling spool with 2" min. till line and 3" min choke line outlets			
<b>6</b> b	2" min. kill line and 3" mi outlets in ram. (Alternate	n. choke line to 6s above.)		
7	Value	Gale [] Plug []	3-1/8"	
8	Gate valve—power operated		3-1/8"	
9	Line to choke manifold		-	3.
10	Valves	Gate C Plug C	2-1/16*	
11	Check valve		2-1/16"	
12	Casing head			
13	Valve	Gale D Plug D	1-13/16*	
14	Pressure gauge with need	le valve		
15	Kill line to rig mud pump m	enticid		2"

ANNULAR PREVENTED BLIND RAMS PIPE RAMS CASING MEAD	
	8

<del>---- --</del>

CONFIGURATION A

OPTIONAL					
16	Flanged valve	1-13/16"			
The state of the s		1-10/10			

# CONTRACTOR'S OPTION TO FURNISH:

- All equipment and connections above bradenhead or casinghead. Working pressure of preventers to be 3,000 psl, minimum.
- Automatic accumulator (80 gallon, minimum) capable of closing BOP in 30 seconds or less and, holding them closed against full rated working pressure.
- 3.BOP controls, to be located near drillers position.
- 4. Kelly equipped with Kelly cack.
- 5.Inside blowout prevventer or its equivalent en derrick floor at all times with proper threads to fit pipe being used.
- 6. Kelly saver-sub equipped with rubber casing protector at all times.
- 7. Plug type blowout preventer tester.
- 8. Extra set pipe rams to fit drill pipe in use on location at all times.
- 9. Type RX ring gaskets in place of Type R.

## MEC TO FURNISH:

- Bradenhead or casinghead and side valves.
- 2. Wear bushing, If required.

### **GENERAL NOTES:**

- Deviations from this drawing may be made only with the express permission of MEC's Drilling Manager.
- 2. All connections, valves, fittings, piping, etc., subject to well er pump pressure must be lianged (suitable clemp connections acceptable) and have minimum working pressure equal to rated working pressure of preventers up through chore. Valves must be full opening and suitable for high pressure mud service.
- 3. Controls to be of standard design and each marked, showing opening and closing position.
- 4. Choken will be positioned so as not to hamper or delay changing of choke beans. Repiscoable parts for adjustable choke, other bean sizes, retainers, and choke weaches to be conveniently located for immediate use.
- All valves to be equipped with handwheels or handles ready for immediate use.
- 6. Choke lines must be suitably anchored.

- 7. Handwheels and extensions to be connected and ready for use.
- 8. Valves adjacent to drilling speci to be kept open. Use outside valves except a emergency.
- 8.All seemiess steel central piping (3000 psi working pressure) to have flexible joints to avoid stress. Places will be permitted.
- Casinghead connections shall not be used except in case of emergency.
- 11.Do not use kill line for routine illi-up operations.