Form 3160-5 June 1990)	DEPARTMENT	O STATES OF THE INTERIOI ND MANAGEMEN		ət	FORM APPROVED Budget Bureau No. 1004-0135
Do not use this fo U	SUNDRY NOTICES AN rm for proposals to drill o se "APPLICATION FOR F	or to deepen or ree	entry to a different re	eservoir.	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE					7. If Unit or CA, Agreement Designation
1. Type of Well		1		50	COCHITI "5" FEDERAL COM
1. Type of Well Oil St Gas Well Other					8. Well Name and No. COCHITI "5" FEDERAL COM #1
2. Name of Operator MARALO, INC.					9. API Well No.
3. Address and Telephone No. P. O. BOX 832, MIDLAND, TX 79702 (915) 684-7441					30-015-27996 10. Field and Pool, or Exploratory Area FORM UNDESTED (POUE SEDINC)
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					EDDY UNDESIG. (BONE SPRING)
UNIT N, 1980' FWL & 660' FSL, SECTION 5, T24S, R29E					EDDY, MM
2. CHECK	APPROPRIATE BOX(s)	TO INDICATE NA	ATURE OF NOTICE	E, REPOR	T, OR OTHER DATA
	TYPE OF SUBMISSION TYPE OF ACTION				
XX Notice o	fIntent	Abandonment Recompletion			Change of Plans
Subseque	ent Report	Plugg	ging Back		Non-Routine Fracturing
Final At	bandonment Notice	L. Casing Repair Altering Casing			Water Shut-Off Conversion to Injection
		U Other			Dispose Water (Noie: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Co give subsurface loca	mpleted Operations (Clearly state all pe tions and measured and true vertical of	rtinent details, and give perti depths for all markers and z	inent dates, including estimated ones pertinent to this work.)*	date of starting	any proposed work. If well is directionally drilled,
OPOSED					
RUPU. Kill well. RU slickline and run blanking plug & set in "F" nipple (2.31") in pkr @ 11,200". 13. RU Halliburton to frac perfs 9800-99 20/40 mesh resin-coaled sand at a ra Shut well in to allow get to break.				ed sand at a rate	3' down 3 'X' tbg w/ 70,000 gals PurGel III carrying 144 of +/- 30 BPM with an anticipated treating pressure of 650
Pull tbg out of pkr & TOH.	Pull tbg out of pkr & TOH. 14. Swab/flow back and evaluate.				·
TIH w/ dump bailer and oump 35 Giff of top of part. 15. Release pkr. TOH w/ tbg. TIH w/ tbg. open-ended, to TOC. Displace hole w/ 15 bbls 10#/ gal mud-laden fluid (to top of liner)				tbg. TIH w/ pro-	duction equipment and place well on production.
	[IH.w/ 4 1/2" CIBP and set @ 10,200'. TIH				
	7 1/2% mud clean-out acid, triple-inhibite				and all that a Baath alwaged off w/CIBP @ 12.2
RU wireline and run GR/CBD/CCL from PBTD to TOC. Contenate to divided on order to the contenate to divide on order to the contenate to				12,202-12,20	<ul> <li>68° OH (Atoka Bank), plugged off w/CIBP @ 12,2</li> <li>04' Atoka Sand, plugged w/pkr + 35' cmt.</li> <li>61' Strawn, plugged w/ CIBP + 35' cmt @ 11,86'</li> </ul>
TIH w/ 4" carrier guns, pr 9881-9884, 9889-9903' (t	emium charges, and shoot 1 JSPF @ 98 otal 46 holes).	00-9819, 9824-9833, 9838-98	344.	11,460-11,5	22' Wolfcamp, open.
TIH w/ 7" pkr on 3 ½" tbg	g to +/- 9750'. Reverse spot acid into tbg	Set pkr.			
Breakdown perfs by pump					
Continue treatment by pum at a rate of +/- 5 BPM.	ping 2000 gals 7 1/2% mud clean-out acid	carrying 92 ball sealers down			
14. I hereby certify that the Signed	foregoing is true and correct	TitleREGULA	ATORY ANALIST		Date0CTOBER 7, 1996
(This space for Federal Approve ORIG. SG Conditions of approval,	D.) ALEXIS C. SWOBODA	TitlePE	TROLEUM ENGINE	EER	Date 10/10/46
	1, makes it a crime for any person kn matter within its jurisdiction.	owingly and willfully to ma	ke to any department or agency	of the United	States any false, fictitious or fraudulent statements

.

CISE

----

14 "..