| Oil Well Well Other 2. Name of Operator | 7. If Unit or CA, Agreement Designation |
|---|--|
| Do not use this form for proposals to drill or to deepen or reentry to a different r Use "APPLICATION FOR PERMIT—" for such proposals SUBMIT IN TRIPLICATE" 1. Type of Well Oil Well Gas Well Other 2. Name of Operator MIDDE 194 | 6. If Indian, Allottee or Tribe Name CESERVOIR. 7. If Unit or CA, Agreement Designation |
| 1. Type of Well Oil Gas Well Well Other 2. Name of Operator MON 08.'94 (C) | |
| Oil Oil Gas Other 2. Name of Operator WOUD8.'94 | |
| MARALO, INC. | GOLD RUSH "30" FED CON #1 8. Well Name and No. |
| 3. Address and Telephone No. | GOLD RUSH "30" FED CON #1. 9. API Well No. |
| HAKUU, IRc. O. 3. Address and Telephone No. O. P. 0. BOX 832, MIDLAND, TX 79702 (915) 68417441 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) | 30-015-28032 10. Field and Pool, or Exploratory Area |
| 1980' FNL & 1980' FEL, SEC 30, T23S, R30E | MILDCAT 11. County or Parish, State |
| 2. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE | E, REPORT, OR OTHER DATA |
| TYPE OF SUBMISSION TYPE O | FACTION |
| Notice of Intent | Change of Plans |
| Subsequent Report Plugging Back | Non-Routine Fracturing Water Shut-Off |
| Final Abandonment Notice | TION Conversion to Injection Dispose Water (Note: Report results of matuple completion on Well Completion or Recompletion Report and Log form.) |
| Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* PROPOSED OPERATION: COMPLETE IN PADUCA SAND RUPU. TIH w/bit, csg scrapers & tbg to PBTD. "Pickle " tbg by pumping 300 gals 15% inhibited, to btm of tbg then reversing out. TOH w/tbg, scrapers & bit. RU wireline. Run GR/CBL/CCL from PBTD to top of liner @ 10,048'. Run w/1000 psi on c to SWSCO GR/CNL/LDT OH log run 9/26/94. TIH (on wireline) w/Halliburton 4 1/2" perma latch pkr w/associated equipment plus 3 3 loaded 4 SPF. Set pkr to position guns to shoot @ 13,625, 13,626, 13,627, 13,637, 13,63 13,644-13,655'. RD wireline. TIH w/tbg to top of pkr. Circulate backside w/"packer" fluid. Sting into pkr. Swab fluid level in tbg down to 6000' to achieve 2000 psi underbalanced condition. Drop firing bar and detonate guns. Monitor tbg pressure. Flow back well and monitor. If stimulation is needed, acidize perfs w/2000 gals 7 1/2% "Morrow" acid (HCL w/clay surfactants) containing 1200 SCF/bbl N₂. Drop 75 ball sealers during acid job for diverse of the clearth of the proceed of the sealers during acid job for diverse. | ssg. Correlate 3/8" TCP guns 13,639 and 10 LL 10 LL 1 |
| down tbg at a rate of +/- 3 BPM. Flush w/N ₂ . 14. I hereby certify that the foregoing is true and correct | |
| Signed Stanthen began Title REGULATORY ANALYST | Date OCTOBER 7, 1994 |
| (This space for Federal or State office use) Approved by (ORIG. SGD.) JOE G. LARA Title PETROLEUM ENG Conditions of approval, if any: | Date 11/4/94 |