

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

1-5-1st

tesia, NM 8710-2834

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

**MARALO, INC.**

3. Address and Telephone No.

**P. O. BOX 832, MIDLAND, TX 79702**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**520' FEL & 1855' FNL, SEC. 30, T23S, R30E**

5. Lease Designation and Serial No.

**NM-81622**

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

**GOLD RUSH "30" FEDERAL #3**

9. API Well No.

**30-015-28671**

10. Field and Pool, or Exploratory Area

**NASH-DRAW; BRUSHY CANYON**

11. County or Parish, State

**EDDY, NM**

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other **ON SITE EQUIPMENT STORAGE**

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

MARALO, INC. REQUESTS AUTHORITY TO STORE MINIMUM SURPLUS TUBULAR GOODS ON THE ABOVE LEASE'S INDIVIDUAL WELLSITES.

IMMEDIATE ACCESS OF SURPLUS EQUIPMENT IS THE MOST EFFICIENT METHOD FOR ONGOING OPERATIONS AND REMEDIAL WORK.

STORING EQUIPMENT AT A CENTRALIZED COMMON SITE IS UNDESIRABLE AND LESS EFFICIENT DUE TO THE UNIQUENESS OF THE EQUIPMENT TO THE WELLSITE. ACCOUNTING DISCREPANCIES CAUSED BY VARYING WORKING INTERESTS IN DIFFERENT WELLBORES WILL ALSO BE ALLEVIATED BY ON-SITE STORAGE.

RECEIVED  
1997 AUG 21 A 10:55  
BUREAU OF LAND MGMT  
CARLSBAD RESOURCE AREA

14. I hereby certify that the foregoing is true and correct

Signed *Dorothea Zagan*

Title **REGULATORY ANALYST**

Date **AUGUST 20, 1997**

(This space for Federal or State office use)

Approved by **(ORIG. SGD.) DAVID R. GLASS**

Title **PETROLEUM ENGINEER**

Date **SEP 17 1997**

Conditions of approval, if any: