Submit 3 Copies to Appropriate			
		of New Mexico	Form C-103
	Enc. gy, Minerals and I	Natural Resources Department	Revised 1-1-89
District Office			
<u>DISTRICT I</u>	OIL CONSEI	RVATION DIVISION	WELL API NO.
P. O. Box 1980, Hobbs, NM 88240	P. O. Box 2088		30-015-29715
<u>DISTRICT II</u>	Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease
811 S. 1st Street, Artesia, NM 88210-2834			State X Fee
DISTRICT III			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410			
			001796
	TICES AND REPORTS		
(DO NOT USE THIS FORM FOR PI			7. Lease Name or Unit Agreement Name
	ERVOIR. USE "APPLICATION		
1. Type of Well	C-101) FOR SUCH PROPOS	SALS)	
Oil Well X Gas Well		_	Poker Lake Unit
2. Name of Operator	Other	ſ	
Bass Enterprises Production Co	mpany		8. Well No 137
3. Address of Operator			9. Pool Name or Wildcat
P. O. Box 2760 Midland, Texas 79702-2760			Forty-Niner Ridge, (Delaware) SW
4. Well Location		···· // // // // // // // // // // // //	
Unit Letter D:	330' Feet From The	North Line and 330'	Feet From The <u>West</u> Line
Section 32 T	ownship 23S	Repara 205 NIMENA	
	0. Elevation (Show whether DF	Range 30E NMPM	Eddy County
·	3125' GL, 3140	•	
11. Check Appr		e Nature of Notice, Report, o	r Other Data
NOTICE OF INTEN	TION TO.		ENT REPORT OF:
TEMPORARILY ABANDON	HANGE PLANS	COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING			
		CASING TEST AND CEMENT JOB	_
OTHER:		OTHER: Spud Date, Surface Casi	ng, TD
12. Describe Description Completed Operation			
 Describe Proposed or Completed Operat work) SEE RULE 1103. 	ions (Cleany state all pertinent (details, and give pertinent dates, including	g estimated date of starting any proposed
Spud @ 1:00 a.m. on 8/7/97.			
Drilled 14-3/4" hole to 617 8/8/97			
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40	ST&C casing set at 612'.		16373970-
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w	ST&C casing set at 612'. ith additives. Tail with 240 sx C		A 16373970772
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40	ST&C casing set at 612'. ith additives. Tail with 240 sx C		A 1907 1907
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w	ST&C casing set at 612'. ith additives. Tail with 240 sx C		1997 IST
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97.) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement,		1997 RECEIVED
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W.) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'.	test casing to 600 psi, OK.	RECEIVED OCD ARTESIA
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200	test casing to 600 psi, OK.	A 1997 RECEIVED OCD - ARTESIA
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50 Cemented with 900 sx 35/65 Poz Circulated 213 sx to surface. W.) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200 O.C. 24 hours.	test casing to 600 psi, OK.	RECEIVED
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50 Cemented with 900 sx 35/65 Poz Circulated 213 sx to surface. W. Drilled 7-7/8" hole to 7442' 8/26/9) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200 O.C. 24 hours. 7.	test casing to 600 psi, OK.	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50 Cemented with 900 sx 35/65 Poz Circulated 213 sx to surface. W. Drilled 7-7/8" hole to 7442' 8/26/9 Ran 95 joints 5-1/2" 15.5# K-55 L) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200 O.C. 24 hours. 7. T&C casing (0-4326'), 52 joints	test casing to 600 psi, OK. sx Class C neat. s 5-1/2" 15.5# J-55 LT&C casing (4326-6	and the second
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50 Cemented with 900 sx 35/65 Poz Circulated 213 sx to surface. W. Drilled 7-7/8" hole to 7442' 8/26/9 Ran 95 joints 5-1/2" 15.5# K-55 L) ST&C casing set at 612'. ith additives. Tail with 240 sx 0 O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200 O.C. 24 hours. 7. T&C casing (0–4326'), 52 joints sandblasted (6600-7442'). DV 	test casing to 600 psi, OK. sx Class C neat. s 5-1/2" 15.5# J-55 LT&C casing (4326-6 / tool @ 5846'.	600'),
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50 Cemented with 900 sx 35/65 Poz Circulated 213 sx to surface. W. Drilled 7-7/8" hole to 7442' 8/26/9 Ran 95 joints 5-1/2" 15.5# K-55 L) ST&C casing set at 612'. ith additives. Tail with 240 sx 0 O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200 O.C. 24 hours. 7. T&C casing (0-4326'), 52 joints sandblasted (6600-7442'). DV 85 sx Class H with additives, Si 	test casing to 600 psi, OK. sx Class C neat. s 5-1/2" 15.5# J-55 LT&C casing (4326-6 / tool @ 5846'.	and the second
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50 Cemented with 900 sx 35/65 Poz Circulated 213 sx to surface. W. Drilled 7-7/8" hole to 7442' 8/26/9 Ran 95 joints 5-1/2" 15.5# K-55 L 19 joints 5-1/2" K-55 15.5# LT&C Cement in two stages: Stage 1) 2 Rig released @ 11:00 p.m. on 8/2 TOC @ 3120' TS, Prep for comp) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200 O.C. 24 hours. 7. T&C casing (0-4326'), 52 joints sandblasted (6600-7442'). DV 85 sx Class H with additives, Si 24/97. letion. 	test casing to 600 psi, OK. sx Class C neat. s 5-1/2" 15.5# J-55 LT&C casing (4326-6 / tool @ 5846'. tage 2) 310 sx 35/65 Poz C with additives	600'),
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50 Cemented with 900 sx 35/65 Poz Circulated 213 sx to surface. W. Drilled 7-7/8" hole to 7442' 8/26/9 Ran 95 joints 5-1/2" 15.5# K-55 L 19 joints 5-1/2" K-55 15.5# LT&C Cement in two stages: Stage 1) 2 Rig released @ 11:00 p.m. on 8/2) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200 O.C. 24 hours. 7. T&C casing (0-4326'), 52 joints sandblasted (6600-7442'). DV 85 sx Class H with additives, Si 24/97. letion. 	test casing to 600 psi, OK. sx Class C neat. s 5-1/2" 15.5# J-55 LT&C casing (4326-6 / tool @ 5846'. tage 2) 310 sx 35/65 Poz C with additives	600'),
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50 Cemented with 900 sx 35/65 Poz Circulated 213 sx to surface. W. Drilled 7-7/8" hole to 7442' 8/26/9 Ran 95 joints 5-1/2" 15.5# K-55 L 19 joints 5-1/2" K-55 15.5# LT&C Cement in two stages: Stage 1) 2 Rig released @ 11:00 p.m. on 8/2 TOC @ 3120' TS, Prep for comp I hereby certify that the information above is true an) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200 O.C. 24 hours. 7. T&C casing (0-4326'), 52 joints sandblasted (6600-7442'). DV 85 sx Class H with additives, Si 24/97. letion. d complete to the best of my know 	test casing to 600 psi, OK. sx Class C neat. s 5-1/2" 15.5# J-55 LT&C casing (4326-6 / tool @ 5846'. tage 2) 310 sx 35/65 Poz C with additives	600'), s, Tail with 400 sx Class C neat with additives.
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50 Cemented with 900 sx 35/65 Poz Circulated 213 sx to surface. W. Drilled 7-7/8" hole to 7442' 8/26/9 Ran 95 joints 5-1/2" 15.5# K-55 L 19 joints 5-1/2" K-55 15.5# LT&C Cement in two stages: Stage 1) 2 Rig released @ 11:00 p.m. on 8/2 TOC @ 3120' TS, Prep for comp I hereby certify that the information above is true an SIGNATURE) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200 O.C. 24 hours. 7. T&C casing (0-4326'), 52 joints sandblasted (6600-7442'). DV 85 sx Class H with additives, Si 24/97. letion. d complete to the best of my know WILLW 	test casing to 600 psi, OK. sx Class C neat. s 5-1/2" 15.5# J-55 LT&C casing (4326-6 / tool @ 5846'. tage 2) 310 sx 35/65 Poz C with additives	600'), s, Tail with 400 sx Class C neat with additives.
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50 Cemented with 900 sx 35/65 Poz Circulated 213 sx to surface. W. Drilled 7-7/8" hole to 7442' 8/26/9 Ran 95 joints 5-1/2" 15.5# K-55 L 19 joints 5-1/2" K-55 15.5# LT&C Cement in two stages: Stage 1) 2 Rig released @ 11:00 p.m. on 8/2 TOC @ 3120' TS, Prep for comp I hereby certify that the information above is true an SIGNATURE) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200 O.C. 24 hours. 7. T&C casing (0-4326'), 52 joints sandblasted (6600-7442'). DV 85 sx Class H with additives, Si 24/97. letion. d complete to the best of my know 	test casing to 600 psi, OK. sx Class C neat. s 5-1/2" 15.5# J-55 LT&C casing (4326-6 / tool @ 5846'. tage 2) 310 sx 35/65 Poz C with additives	600'), s, Tail with 400 sx Class C neat with additives.
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50 Cemented with 900 sx 35/65 Poz Circulated 213 sx to surface. W. Drilled 7-7/8" hole to 7442' 8/26/9 Ran 95 joints 5-1/2" 15.5# K-55 L 19 joints 5-1/2" K-55 15.5# LT&C Cement in two stages: Stage 1) 2 Rig released @ 11:00 p.m. on 8/2 TOC @ 3120' TS, Prep for comp I hereby certify that the information above is true an SIGNATURE TYPE OR PRINT NAME Tam (This space for State Use)) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200 O.C. 24 hours. 7. T&C casing (0-4326'), 52 joints sandblasted (6600-7442'). DV 85 sx Class H with additives, Si 24/97. letion. d complete to the best of my know <i>M Wilbur</i> <i>i</i> L. Wilber 	test casing to 600 psi, OK. sx Class C neat. s 5-1/2" 15.5# J-55 LT&C casing (4326-6 / tool @ 5846'. tage 2) 310 sx 35/65 Poz C with additives //edge and belief. TITLE: Production C	600'), s, Tail with 400 sx Class C neat with additives.
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50 Cemented with 900 sx 35/65 Poz Circulated 213 sx to surface. W. Drilled 7-7/8" hole to 7442' 8/26/9 Ran 95 joints 5-1/2" 15.5# K-55 L 19 joints 5-1/2" K-55 15.5# LT&C Cement in two stages: Stage 1) 2 Rig released @ 11:00 p.m. on 8/2 TOC @ 3120' TS, Prep for comp I hereby certify that the information above is true an SIGNATURE) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200 O.C. 24 hours. 7. T&C casing (0-4326'), 52 joints sandblasted (6600-7442'). DV 85 sx Class H with additives, Si 24/97. letion. d complete to the best of my know K WILLW i L. Wilber WILDW	test casing to 600 psi, OK. sx Class C neat. s 5-1/2" 15.5# J-55 LT&C casing (4326-6 / tool @ 5846'. tage 2) 310 sx 35/65 Poz C with additives //edge and belief. TITLE: Production C	600'), s, Tail with 400 sx Class C neat with additives.
Drilled 14-3/4" hole to 617' 8/8/97 Ran 15 joints 11-3/4" 42# WC-40 Cemented with 200 sx Class C w Circulated 140 sx to surface. W. Drilled 11" hole to 3449' 8/14/97. Ran 80 joints 8-5/8" 28# WC-50 Cemented with 900 sx 35/65 Poz Circulated 213 sx to surface. W. Drilled 7-7/8" hole to 7442' 8/26/9 Ran 95 joints 5-1/2" 15.5# K-55 L 19 joints 5-1/2" K-55 15.5# LT&C Cement in two stages: Stage 1) 2 Rig released @ 11:00 p.m. on 8/2 TOC @ 3120' TS, Prep for comp I hereby certify that the information above is true an SIGNATURE) ST&C casing set at 612'. ith additives. Tail with 240 sx C O.C. 20.5 hours. Drill cement, ST&C casing set at 3448'. C with additives. Tail with 200 O.C. 24 hours. 7. T&C casing (0-4326'), 52 joints sandblasted (6600-7442'). DV 85 sx Class H with additives, Si 24/97. letion. d complete to the best of my know <i>M Wilbur</i> <i>i</i> L. Wilber 	test casing to 600 psi, OK. sx Class C neat. s 5-1/2" 15.5# J-55 LT&C casing (4326-6 / tool @ 5846'. tage 2) 310 sx 35/65 Poz C with additives //edge and belief. TITLE: Production C	600'), s, Tail with 400 sx Class C neat with additives.