N.M. Oil Com. Division

811 S. 1st Street FORM APPROVED **UNITED STATES** Form 3160-5 OMB No. 1004-0135 Artesia, NM 88210-2834 Expires November 30, 2000 (August 1999) DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** 5. Lease Serial No. NM-90847 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well 8. Well Name and No. Oil Well Gas Well Other Big Freddy Unit #1 2. Name of Operator 9. API Well No. Yates Petroleum Corporation 30-015-29<u>734</u> 3b. Phone No. (include area code) 3a. Address 10. Field and Pool, or Exploratory Area 505-748-1471 105 S. 4th St. - Artesia, NM 88210 Wildcat Cisco (gas)/ Indian Basin Upper Penn, SW 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 1980' FNL & 1980' FEL of Section 10-T23S-R22E (Unit G, SWNE) Eddy Co., NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Water Shut-Off Production (Start/Resume) Deepen Acidize Well Integrity Reclamation Fracture Treat Notice of Intent Alter Casing X Other Commingle Recomplete ■ New Construction Casing Repair Subsequent Report Strawn & Cisco Temporarily Abandon Plug and Abandon Change Plans ■ Water Disposal Plug Back Final Abandonment Notice Convert to Injection Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Propose to commingle perforations 7368-7543' (Cisco) and 8671-9178' (Strawn) as follows: Load tubing. Nipple down tree and nipple up BOP. Unset packer and 7328'. TOOH with tubing, packer and RBP. GIH to RBP at 7588', latch onto RBP. 3. GIH with packer with on/off tool and 1.875" profile nipple. Set packer at 7328' and pressure test. Nipple down BOP and nipple up tree. 5. Swab well in. Place well into production.

Downhole commingling order no.: DHC-1834

NOTIFY OCD-ARTESIA (505-748-1283) AND ALEXIS SWOBODA W/BLM-ROSWELL (505-627-0228) WHEN

WORK IS COMMENCED 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Operations Technician Title Rusty Kleir Date December 20, 1999 Signature / THIS SPACE FOR FEDERAL OR STATE OFFICE USE

(ORIG. SGD.) ALEXIS C. SWOBODA Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

METROLEUM ENGINEER.

Office

ROSWELL, NM

DEC 51 1888

BECEINED