ubmit 3 Copies

Appropriate

Istrict Office

State of New Mexico Energy, Minerals and Natural Resources Department

115F	
617,	Form C-103
	Revised 1-1-89

2	RIC	II .			
O.	Box	1980,	Hobbs,	NM	88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO.		
30-015- 28637 2	29763	
5. Indicate Type of Leas	e	
	STATE FEE	

ISTRICTI			30-015- 28637 29743				
O. Drawer DD, Artesia	L NM 88210	2 3, 1 10 11	icaco	07504-2000	5. Indicate Type	1 1	
<u>ISTRICTIII</u> XXX Rio Brazos Rd., A z	iec, NM 87410				6. State Oil & Ga	STATE	FEE
					d Sale of the Ga	a Lease 140,	
SU DO NOT USE THIS	JNDRY NOTICE	S AND REPORTS O	N WE	LLS			
DIF	LEHENT HEZEHAO	SALS TO DRILL OR TO D R. USE "APPLICATION F	OR PE	VOR PLUG BACK TO A	7. Lease Name or	Unit Agreement Name	
Type of Well:	(FORM C-101	FOR SUCH PROPOSAL	S.)				
OUT XX	GAS WELL				 Harroun 15		
Name of Operator	*at []	OTHER					
Pogo Produci	ng Company				8. Well No.		
Address of Operator		•			9. Pool name or W	Vildeat	
P. O. Box 10 Well Location	340, Midland	TX 79702-7340			Cedar Canyo	on Delaware	
	1 330	Feet From The Sout	า		<u></u>		
		rea rion the		Line and330	Feet From	The West	Line
Section 15	777777777777	Township 24S	Ra	nge 29E N	ІМРМ	Eddv	County
		10. Elevation (Show)	vhether	DF, RKB, RT, GR, etc.)		V/////////////////////////////////////	7//////
	Check App	ropriete Day to Indi	4- 3	I CN D			
NOTI	CE OF INTEN	TION TO:	cate 1	Nature of Notice, Re			
		HON TO.		SUBS	SEQUENT RI	EPORT OF:	
FORM REMEDIAL W	ORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING	
PORARILY ABANDO	on 🔲	CHANGE PLANS	\Box	COMMENCE DRILLING	OPNS.	PLUG AND ABANDO	NIMENIT
LOR ALTER CASING	3 N					LOG AND ABANDO	IAINICIA I
ER:			$\overline{}$	CASING TEST AND CEN			
			\cup	OTHER: Add Delaw			XX
Describe Proposed or C work) SEE RULE 1103	Completed Operations (3.	Clearly state all pertinent des	ails, and	d give pertinent dates, includir	eg estimated date of s	starting any proposed	
01/22/98	Set RBP @ 5	140' Perf Delawara	407/	1, 56, (54 - 20, 4; -1	1) 0 5040	1.541./10	
	holes).	140 . I chi Delawah	77/°	4'-86' (2450" dia 1	notes) & 5048	1-54" (1250"	dia ,
01/23/98	,	gals 7-1/2% HCL.	Swał	n test			
01/28/98	Frac w/ 73,50	0# 16/30 sand. Flow	v wel	l back.			
01/30/98	Set RBP @ 49	950'. Perf Delaware	4926	5'-38' (2450" dia 1	noles). Acdz s	v/ 500 gals 7-1/	20/
	HCL. Swab t	est. Latch onto RBI	P @ 4	950' & POOH.	11002	W 500 gais 7 17.	270
01/31/98	Swab test.		-				
02/03/98	Run production	on eqpt. Put well on	pumj	p.	ruit — e		
					4		
						1000	
					RECE		
eby ceruly that the inform	zion sbove is true and fo	nplete to the best of my knowled	ge and b	elid.		RTESIA	
ATURE BAN	ntt	Q	TITT F	Senior Operation	ons Eng.	3/11/98	3
В.	arrett L. Smi	th					
OR FRINT NAME		VII		(9.	15)685-8100	TELEPHONE NO.	

space for State Use)

ORIGINAL SIGNED BY TIM W. GUM DISTRICT II SUPERVISOR

me -