

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

KUKUI Operating Company

3a. Address

203 W. Wall Street, Suite 810
Midland, TX 79701

3b. Phone No. (include area code)

915-687-6200

4. Location of Well (footage, Sec., T., R., M., or Survey Description)

2,180' FWL & 660' FSL Sec. 35 - T23S - R29E

Oil Cons.

J.M. Div-Dist. 2

1301 W. Grand Avenue
Artesia, NM 88210

5. Lease Serial No.

NMNM - 103604

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Goodnight 35 Federal #1

9. API Well No.

30-015-31096

10. Field and Pool, or Exploratory Area

Nash Draw Delaware, Southwest

11. County or Parish, State

Eddy, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input checked="" type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BLA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

PLUG BACK LOWER BRUSHY- AVION & RECOMPLETE UPPER BRUSHY - H.B.

1/11/02 - 1/20/02

MIRU workover rig. POH with rods, pump & tubing. Set 7" CIBP @ 6,350'. Dump bail 4 sacks cement on plug. Perforate Upper Brushy Canyon - H.B. sand 5,874 - 5,890', 4 spf. Acidize perfs with 1,000 gals 15% HCL diverted with 80 each 1.3 s.g ball sealers. Frac with 19,000 gals YF-130 and 25,642 lbs. 16/30 sand. Swab test 3 days. Placed well on pump. RDMO rig.

ACCEPTED FOR RECORD

FEB 28 2002

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Larry K. Strider

ALEXIS C. SWOBODA
PETROLEUM ENGINEER

Title Western District Manager

Signature

L.K. Strider

Date 2/21/02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

RECEIVED

2009 FEB 25 AM 8:48

RECEIVED
FEB 25 2009
FBI - NEW YORK