

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.
30-015-31466

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
UB 464

7. Lease Name or Unit Agreement Name:
OK? Honest John State

8. Well No.
1

9. Pool name or Wildcat
Under Carlsbad Morrow, South

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3484

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
OXY USA WTP Limited Partnership 192463

3. Address of Operator
P.O. BOX 50250 MIDLAND, TX 79710-0250

4. Well Location
Unit Letter G : 1980 feet from the NORTH line and 1700 feet from the EAST line
Section 18 Township 23S Range 26E NMPM County Eddy

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

See other side

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE REGULATORY ANALYST DATE 3/23/01

Type or print name DAVID STEWART

Telephone No. 915-685-5717

(This space for State use)

APPROVED BY BOB ORIGINAL SIGNED BY TIM W. GUN DISTRICT # 4 TITLE SUPERVISOR DATE 3/27/2001

Conditions of approval, if any:

NOTIFIED NMOCD 3/13/01 OF SPUD. MIRU UTI 207, SPUD WELL @ 1400hrs MST
3/14/01. DRILL 17-1/2" HOLE TO 156' & LOST RETURNS, DRY DRILL TO TD @ 719',
3/15/01, PUMP SWEEP. RIH W/ 13-3/8" 48# H40 CSG, SET @ 718'. M&P 200sx CL H
W/ 10% A10B + 10# LCM-1 + .25#/sx CELLOFLAKES + 1% CaCl₂ FOLLOWED BY 366sx
65/35 C/POZ W/ 6% BENTONITE + 2% CaCl₂ + 5#/sx LCM-1 FOLLOWED BY 200sx CL C W/
2% CaCl₂, DISP W/ FW, PLUG DOWN 3/16/01, CEMENT DID NOT CIRC, WOC-5hrs, NMOCD
NOTIFIED BUT DID NOT WITNESS. RIH W/ TEMP SVY, TOC @ 116'. RIH W/ 1" TO
155', M&P 50sx CL C W/ 5% CaCl₂, POOH, WOC-2hr. RIH & TAG @ 108', M&P 50sx CL
C W/ 5% CaCl₂, POOH, WOC-2hr. RIH & TAG @ 90', M&P 150sx CL C W/ 2% CaCl₂,
CIRC 20sx CMT TO PIT, NMOCD NOTIFIED BUT DID NOT WITNESS. CUT OFF CASING,
WELD ON WELL HEAD, TEST TO 500#, OK. NU BOP & TEST BOP & CASING TO 500#, OK.
TEST PIPE RAMS & HYDRIL TO 500#, OK. RIH & TAG, DRILL OUT & DRILL AHEAD
3/17/01.

DRILL 12-1/4" HOLE TO TD @ 2807', 3/20/01, CHC. RIH W/ 9-5/8" 36# CSG & SET @
2807'. M&P 780sx 35/65 POZ/C W/ 6% BENTONITE + 2% CaCl₂ + 5#/LCM-1 FOLLOWED
BY 200sx CL C CMT W/ 2% CaCl₂, DISP W/ FW, PLUG DOWN 3/20/01, CIRC 194sx TO
PIT, WOC-6hrs. NMOCD NOTIFIED BUT DID NOT WITNESS. CUT OFF CSG & INSTALL B
SEC, TEST TO 1500#, OK. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS,
CHOKE LINES, CHOKE MANIFOLD AND SAFETY VALVES TO 5000#, OK. TEST HYDRIL, MUD
LINES AND CSG TO 2500#, OK. TOTAL WOC-18hrs. RIH, DO CMT & SHOE, DRILL NEW
FORMATION, TEST CSG, OK. DRILL AHEAD 3/21/01.