

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-015-31589
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V5445
7. Lease Name or Unit Agreement Name OXY Boo State
8. Well No. 1
9. Pool name or Wildcat Undeg. Carlsbad Morrow, South
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3333'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator OXY USA WTP Limited Partnership
3. Address of Operator P.O. Box 50250 Midland, TX 79710-0250
4. Well Location Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line Section 9 Township 23S Range 26E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3333'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☒
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SEE OTHER SIDE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Sr. Regulatory Analyst DATE 12/5/01

TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915-685-5717

(This space for State Use)

**ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR**

APPROVED BY Tim W. Gum TITLE District II Supervisor DATE DEC 11 2001

CONDITIONS OF APPROVAL, IF ANY:

ATTACHMENT C-103
OXY USA WTP LP
OXY BOO STATE #1
SEC 9 T23S R26E
EDDY COUNTY, NM

NOTIFIED NMOCD & FAA 11/20/01 OF SPUD. MIRU PATTERSON/UTI 508, SPUD WELL @ 1830hrs 11/20/01, DRILL 17-1/2" HOLE TO TD @ 705', 11/21/01, PUMP SWEEP. RIH W/ 13-3/8" 48# H40 CSG, SET @ 705'. M&P 200sx CL H W/ 10% A10B + .25#/sx CELLOFLAKES + 10#/sx LCM-1 + 1% CaCl₂ FOLLOWED BY 400sx 65:35 C/POZ W/ 6% BENTONITE + 2% CaCl₂ + .25#/sx CELLOFLAKES + 5#/sx LCM FOLLOWED BY 200sx CL C W/ 2% CaCl₂, DISP W/ FW, PLUG DOWN 11/22/01. CMT DID NOT CIRC, WOC-4hr, NMOCD NOTIFIED BUT DID NOT WITNESS. RIH W/ TEMP SVY, TOC @ 262'. RIH W/ 1" & TAG SOLID @ 250', UNABLE TO GO ANY DEEPER, M&P 100sx CL C W/ 4% CaCl₂, POOH, WOC-1hr. RIH & TAG @ 150', M&P 100sx CL C W/ 4% CaCl₂, POOH, WOC-1hr. RIH & TAG @ 124', M&P 175sx CL C W/ 4% CaCl₂, CIRC 15sx CMT TO PIT. CUT OFF CASING, WELD ON WELL HEAD, TEST TO 1000#, OK. NU BOP & TEST BOP & CASING TO 500#, OK. TEST PIPE RAMS & HYDRIL TO 500#, OK. RIH & TAG, DRILL OUT & DRILL AHEAD 11/23/01.

DRILL 12-1/4" HOLE TO TD @ 2829', 11/27/01, CHC. RIH W/ 9-5/8" 36# K55 CSG & SET @ 2825'. M&P 811sx 65:35 C/POZ W/ 6% BENTONITE + 2% CaCl₂ + .25#/sx CELLOFLAKES + 5#/sx LCM FOLLOWED BY 200sx CL C CMT W/ 1% CaCl₂, DISP W/ FW, PLUG DOWN 11/28/01. CIRC 135sx CMT TO SURFACE, WOC-6hrs, NMOCD NOTIFIED BUT DID NOT WITNESS. CUT OFF CSG & INSTALL B SEC, TEST TO 1500#, OK. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, CHOKE LINES, CHOKE MANIFOLD AND SAFETY VALVES TO 5000#, OK. TEST HYDRIL, MUD LINES AND CSG TO 2500#, OK. TOTAL WOC-18hrs, RIH, DO CMT & SHOE, DRILL NEW FORMATION, TEST CSG, OK. DRILL AHEAD 11/29/01.