

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87910

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

CONFIDENTIAL

Form C-103
Revised March 25, 1999

WELL API NO.

30-015-32320

5. Indicate Type of Lease

STATE ☐ FEE ☐ P ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Clyde

8. Well No.

1

9. Pool name or Wildcat

Carlsbad; Morrow, South Pre Gas

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☒ Amended Report

2. Name of Operator

Concho Oil & Gas Corp.

3. Address of Operator

110 W. Louisiana, Ste 410, Midland, TX 79701

4. Well Location

Unit Letter P : 660' feet from the South line and 990' feet from the East line

Section 22 Township 23S Range 26E NMPM County Eddy

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3286' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Set Protective Casing ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

8/10-11/02- Drilled 8 3/4" hole to 9589'. Ran 7" 26# HCL-80 LTC casing & set at 9587'. Cement casing in 2 stages as follows:

1st stage: Lead- cement casing with 600 sxs 30/65 Poz H + 6% gel + 5% salt + 5# gil + 3/10% FL52, tail- w/100 sxs "H" + 1/10% R-3.

2^{ns} stage: Lead- 350 sxs 50/50 Poz C + 10% gel + 5% salt + 5# gil + 1/4 PPS cello FR, tail- w/100 sxs "C" neat.

Circ 149 sxs. ND BOP. WOC (8 hrs). Test to 4000#- Ok. NU BOP & test BOP 3500#- Ok.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dora Bustamante TITLE Production Analyst DATE 8/13/02

Type or print name Dora Bustamante

Telephone No. (915) 683-7443

(This space for State use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY [Signature] TITLE DATE AUG 26 2002

Conditions of approval, if any: