




- Wind Direction Indicators (wind sock or streamers)
- △ H2S Monitors (alarms at bell nipple and shale shaker)
- Briefing Areas
- Remote SOP Closing Unit
- Sign and Condition Flags

EXHIBIT "D"
RIG LAY OUT PLAT

UNIT PETROLEUM COMPANY
GOURLEY FEDERAL # 3
UNIT "H" SECTION 28
T22S-R28E EDDY CO. NM