	-	-	
			ì

## (SUBMIT IN TRIPLICATE)

Land Office_	188	14008			
Lease No. 061716					
Unit					

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AI	ND REPORTS ON WELLS				
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY				
Att of the second of the secon	Cancary 13, 1956 , 19				
Well No. 3 is located 330 ft. from  (14 Sec. 1 26.)  (15 Sec. and Sec. No.) (Twp.) (R  11 Cost  (Field) (County or 8)	${N \brace S}$ line and 30ft. from ${W \brack W}$ line of sec. 1  Subdivision (State of Terrison)				
The elevation of the derrick floor above sea leve	l is 3730 ft.				
DETAILS OF WORK					
pointe, and all out	weights, and lengths of proposed casings; indicate mudding jobs, cement= er important proposed work)				
as a conductor string. of tole of the lehaware sand, expected to well to dry it will be	t 75' of 8-5/8" casing will be set will then be drilled to test the top of a approximately 900-1000'. If in conformance with 0.5.0.5. regr 5 as casing will be cemented on top 6.				
Company G. C. Saver	iting by the Geological Survey before operations may be commenced.				
Address Box 1014					
Jurisbie, ew exico	Ву				
7.6 Centere	Title				