April 24, 1957

0. S. Harroun 601 Riverside Drive Carlsbad, New Mexico

Dear Sir:

In checking our files I find that we have not received form C-103, Miscellaneous reports on wells, on your Leeman No. 1 in Section 10-26S-24E, or John Mayes No. 1. in Section 9-26S-24E.

Please submit in triplicate, stateing how much pipe was ran, and also how much cement was used, or anything that has been done to the well during drilling.

See rule 1106 Miscellaneous report on wells, Page 44, in Rules & Regulations Inclosed.

Yours very thuly,

OIL CONSERVATION COMMISSION

M. L. Armstrong, Supervisor, District No. 2

MLA/jn

Enclosure