

Form 100-10
(May 1963)

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

U.S. GOVERNMENT PRINTING OFFICE: 1963 O 42-214-0

U.S. GOVERNMENT PRINTING OFFICE: 1963 O 42-214-0

1. LEASE DESIGNATION AND SERIAL NO.

L.C. 061716

2. IF INDIAN, ALLOTTEE OR TRIBE NAME

3. UNIT AGREEMENT NAME

4. FARM OR LEASE NAME

Government "134"

5. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Washington Ranch (Morrow)

11. SEC., T., R., M., OR ALK. AND

SECTION OR AREA

Section 12-26S-24E

12. COUNTY OR PARISH, 13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

THE SUPERIOR OIL COMPANY

3. ADDRESS OF OPERATOR

P.O. BOX 71, CONROE, TEXAS 77301

4. LOCATION OF WELL (Report location, clearly and in accordance with any State requirements.)

(Use also space 17 below.)
At surface

CON 24 1977
O. G. G.
ARRESTA, OFFICE

1980' FNL & 660' FEL OF SECTION 12

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, ST, GR, etc.)

RKB: 3879

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

STOP WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

☐
☐
☒
☐
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐
☐

☐
☐
☐
☐
☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and some pertinent to this work.)*

Well has been shut-in since 5-21-75. Present perforations are 7452-57, 7462-64, 7470-78. Present PBTD is 7520'. Top of cement outside 7" casing is estimated from temperature survey at 6000'. Intermediate 9-5/8" casing is cemented from 4663' to surface. Surface 13-3/8" casing is cemented from 451' to the surface.

Plugging procedure will be to displace fluid in hole to mud laden fluid and equalize a 35 sack cement plug from 7480' to about 7290'. Recover as much 7" casing as practical. Equalize a 35 sack cement plug from 4713' to about 4610'. Cut off casing at surface if necessary and place 10 sack cement plug in top of casing. Weld a steel plate on top of 9-5/8" casing and install a steel marker at least 4" in diameter extending at least 4 feet above ground level. Mark the steel marker showing the following information:



Government 134#1 X-sec 12-26S-24E
Superior Oil Co.
Eddy, Co. N.M.

RECEIVED

JUN 22 1976

U. S. GEOLOGICAL SURVEY
ARRESTA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

P. R. Stewart

TITLE OPERATIONS ENGINEER

DATE

JUNE 22, 1976

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

Joe H. Lara

TITLE

ACTING DISTRICT ENGINEER

DATE

DEC 7 1976

*Approved for downhole plugging only,
It may be for surface restoration
without further approval.*

*See Instructions on Reverse Side

☒	☒	☒	☒
☒	☒	☒	☒
☒	☒	☒	☒
☒	☒	☒	☒

015:0460134