


NOBLE AND COMPANY

N



S

Company

W.A. Snyder

Farm Name

Pecos

Well No. 1

Sec.

15

Twp

25

Range

28

County

Eddy

Feet from Lines:

N. 1980 S.

660 E.

W.

Elevation

Method

Contractor

Scout

Spudded

Completed

7-19-37

I. P.

CASING

5-3	2815	5

ACID RECORD

Gals.

Prod.	Date
Prod.	Date
T. A.	T. S.
T. P.	T. D.

DATE		DATE	
12-14	TD 2808 Rep. 28	MAR 8 - 1938	TD 3220
12-20	drill ahead		
12-20	TD 2819	3-15	TD 3276 sand & water
12-28	TD 2828	MAR 22 1938	TD 3297 sand S.D.
1-4	TD 2960	MAR 29 1938	only line, increased gas
JAN 11	TD 3000	APR 5 1938	TD 3297 sand S.D.
1-18	TD 3012		TD 3300 sand S.D.
1-25	TD 3072	APR 12 1938	tools in hole W.D.
2-1	TD 3125	APR 19 1938	new drill line
2-8	TD 3138		TD 3306 sand S.D. over
	est 1000 gas	4-26	TD ✓
	TD 3138	MAY 3 - 1938	✓
2-15	TD 3138	MAY 7 1938	✓
FEB 22 1938	TD 3138	MAY 24 1938	✓
	up further	5-31	✓
MAR 1 - 1938	TD 3179	JUN 7 - 1938	✓
	show clear to 1340	JUN 14 1938	✓
	est 2000 gas	JUN 21 1938	✓
		JUN 28 1938	✓
		7-5	✓

LOG

[illegible]