

T. F. Vanderlaan

I inspected your dry hole in 21W-76W of S-16-T36-R28 in Eddy County N.M. Found there was no location on the 4" marker - we need $\frac{3}{4}$ " S T & R that should be put on so it will be permanent with a torch or steel stencil. I also found an open hole just north of dry hole this hole has casing in it. It must have been a water well if you left this well for the rancher please have him to sign a letter that he take the responsibility of this well

Will you please take care of this matter at once

M.L.A.