


(SUBMIT IN TRIPLICATE)



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **LC070085**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	*
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 7, 19 59

Well No. **21-14 Superior Federal** is located **660** ft. from **[N]** line and **660** ft. from **[Ex]** line of sec. **15**
SW of SW 15 **25S** **29E**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
W. C. [Signature] **LEWY COUNTY** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3040** ft. **CL**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set plug of 10 sacks TD, 10 sacks base salt, 7" set at 1517' pulled 1460' mark
10 sack plug 1460'; 8" set at 1273' pulled 810' set 10 sack plug at 800'; 10 3/4 set at
576' pulled 508' set 10 sack plug at 508'; 13 3/8 set at 249' pulled 249' set
10 sack plug at 240' set 25 sacks at surface. set marker; cleaned location

(Done as per telephone conversation)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **J. Glen Bennett**

Address **305 W. Illinois**

Midland, Texas

By *[Signature]*

Title _____