	~~·.	- *		
Form 9-331a	N.	M. O. C. C. COPY	Budget Bureau No. 42-R358.4. Approval expires 12-31-60.	
(Feb. 1951)	(CIIDMP	IN TRIPLICATE	Land Office	
		0 6.1	Lease No. LC -066074-B	
PROVED		ED STATES	"O" D	
	DEPARTMEN	T OF THE INTERIOR	Unit	
SEP 21 1901	GEOLO	GICAL SURVEY	R E -	
BRUNN/F	FFR		Det 4 1961	
CTING DISTRICT ENGIN			- 1	
SU	NDRY NOTICES A	ND REPORTS ON	WELLS D. C. D. D.	
	TO DRILL	SUBSEQUENT REPORT OF WATER		
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE				
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	<u>.</u>	
NOTICE OF INTENTION	TO ABANDON WELL			
	(INDICATE ABOVE BY CHECK MARK	NATURE OF REPORT, NOTICE, OR OTHER		
	,			
3	\$550-210-0	1	June 16, 19 61	
Schran-Fed	eral			
Well No. 1	is located 660 ft. from	1980 ft. from $1980$ ft. from $1980$	$\sum_{i=1}^{E}$ line of sec. 12	
9-19				
SW/4 Sec. and Sec. 1	12 T-26-S R- No.) (Twp.) (	-29-E IMPM Range) (Meridian)		
Brushy Draw	(Und.) Eddy (County or		New Mexico	
(Field)	(County or	Subdivision)	(State or Territory)	
The elevation of th	ne derrick floor above sea lev	al : - 3036 4		
The elevation of th	ie deffick noor above sea lev	er 18 <u>1999</u> , 11.		
		LS OF WORK		
State names of and expec	ted depths to objective sands; show size ing points, and all ot	s, weights, and lengths of proposed cas her important proposed work)	ings; indicate mudding jobs, cement-	
			RECEIVED	
Mudded hole. Set following cement plugs: 20 sxs - 3164'-3314'		plugs:	h there have a to have been been been been been been been be	
			JUN 2 8 1961	
35 sxs - 900'-1050'			U. S. ALVIL - DAL SURVEY	
35 sxs- 450'-600' 15 sxs - Top of surface casing.		MALEA, ALW MEXICO		
Recovered 28	$07' \text{ of } 5\frac{1}{2}^{\mu} \text{ casing.}$	ace casting.		
Plac ed 4" m	arker. Pits have not p	resently been leveled.	. First opportunity	
when equipment	at is available, locati	on will be leveled.		
I understand that this	plan of work must receive approval in v	writing by the Geological Survey before	operations may be commenced	
			operations may be commenced.	
Company Curtis	s hankamer			
Address 1422 Bank	of the Southwest Nldg	•		
Houston 2	, Texas	By Chil	1. Kanham	
			Hankamer	
		Title Engin	leer	
			GP0 862040	
			Gru 602040	