ATTACHMENT REQUEST FOR ALLOWABLE (DISTILLATE) FEDERAL_J.F. HARRIGON NO. 1 2-5-54

Upon completion the well would not flow continously on a choke and the flow was regulated by an intermittent clock control which was regulated to 2, 30 minute flows each day. The well was flowed by this method until it ceased flowing on January 15, 1954. The flow having continously decreased since completion date. The well has been flowed several times since January 15th, after having been shut in a number of hours to allow tubing pressure to build up. The last flow was on January 28th at which time it produced l_2^2 barrels of distillate and a very small amount of gas after having been shut in 69 hours with a shut in tubing pressure of 1150#.

We are requesting an allowable for the well in order to clear storage, prior to moving a rig on the well for remedial work.