Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

811 S. 1r Street Artesia, Nul 88210-2834 MAPPROVED 0MB No. 1004-0135

CISK

Expires November 30, 2000 **BUREAU OF LAND MANAGEMENT** 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS NMLC064756 Do not use this form for proposals to drill or to re-enter an If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side 7. If Unit or CA/Agreement, Name and/or No. Type of Well Oil Well (Gas Well , Other 8. Well Name and No. Name of Operator R.T. WILSON FEDERAL NO. 3 AGHORN OPERATING, INC. API Well No. 3a. Address 300150586600 S1 P.O. BOX 12663 3b. Phone No. (include area code) ODESSA, TX. 79768 10. Field and Pool, or Exploratory Area (915) 550-0804 Location of Well (Footage, Sec., T., R., M., or Survey Description) MASON DELAWARE NORTH 1984' FNL & 660' FEL. SECTION 24, UNIT H 11. County or Parish, State TOWNSHIP -26- SOUTH, RANGE -31- EAST EDDY, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Acidize Deepen Production (Start/Resume) ■ Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation ■ Well Integrity Casing Repair ☐ New Construction ☐ Recomplete Other Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back ■ Water Disposal Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) THE WELL IS PRESENTLY INACTIVE. WE ANTICIPATE RETURNING THE WELL TO ACTIVE PRODUCING STATUS BY APRIL 15, 2001 BUT NO LATER THAN MAY 1, 2001. OPERATIONS WILL INCLUDE PULLING THE DOWNHOLE EQUIPMENT TO REPAIR AND REPLACE RODS, TUBING AND PUMP AS NEEDED, INSTALL ELECTRIC MOTOR AND PANEL AND RETURN WELL TO PRODUCTION. BOND COVERAGE DATES 10/2000 10/2001 BLM BOND FILE NO. NM2750 SURETY BOND NO. 0436348 BAIG SGD) DAVID A, GLASS 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) FROSTY GILLIAM, Title PRESIDENT JR. Signature Date 4-12-01 THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any perso States any false, fictitious or fraudulent statements or representations as to any matter within its

Approval Subject To Putting Well On Continuous **Production And Keeping Well On Continuous** Production.